

**MIL-STD-19**

**20 October 1955**

**SUPERSEDING**

**JAN-E-251**

**26 August 1945**

**MILITARY STANDARD**  
**MARKING OF CONNECTIONS**  
**FOR ELECTRIC ASSEMBLIES**



**MIL-STD-195**  
**29 October 1963**

**OFFICE OF THE ASSISTANT SECRETARY OF DEFENSE**  
**WASHINGTON 25, D. C.**

**Supply and Logistics**

**Marking of Connection for Electric Assemblies**

**MIL-STD-195**

1. This standard has been approved by the Department of Defense for use by the Departments of the Army, the Navy, and the Air Force.

2. In accordance with established procedure, this Standardization Division has designated the Corps of Engineers, Bureau of Ships, and the Air Force, respectively, as Army-Navy-Air Force custodians of this standard.

3. This standard is mandatory for use effective 1 February 1966, by the Departments of the Army, the Navy, and the Air Force.

4. Recommended corrections, additions, or deletions should be addressed to the Standardization Division, Office of the Assistant Secretary of Defense (Supply and Logistics), Washington 25, D. C.

**CONTENTS**

- 1 SCOPE**
  - 1.1 Scope**
  - 1.2 Purpose**
- 2 REFERENCED DOCUMENTS**
- 3 DEFINITIONS**
  - 3.1 Definitions (for the purpose of this standard)**
- 4 GENERAL REQUIREMENTS**
  - 4.1 Use of letters, numerals and symbols**
  - 4.2 Marking nomenclature**
  - 4.3 Method of marking**
  - 4.4 Size of marking**
  - 4.5 Size and location of subscripts**
  - 4.6 Use of subscript numerals**
- 5. DETAIL REQUIREMENTS**
  - 5.1 D.C. generators**
  - 5.2 D.C. motors**
  - 5.3 A.C. generators and synchronous motors**
  - 5.4 Marking of A.C. polyphase induction motors**
  - 5.5 Synchronous converters and dynamotors**
  - 5.6 Constant potential transformers**
  - 5.7 Connection diagrams**
  - 5.8 Motor starters and controllers**
  - 5.9 Power supplies, metallic rectifier**
  - 5.10 Regulator sets, generator voltage**

**FIGURES**

- Figure**
- 1 Series generator without commutating field**
  - 2 Shunt generator with commutating field**
  - 3 Compound generator without commutating field**
  - 4 Compound generator with commutating and compensating fields**
  - 5 Shunt generator without commutating field**
  - 6 Shunt generator with commutating and compensating fields**
  - 7 Compound generator with commutating field, but without equaliser connection**
  - 8 Three-wire shunt generator without commutating field**
  - 9 Three-wire shunt generator with commutating field**
  - 10 Three-wire compound generator without commutating field**
  - 11 Three-wire compound generator with commutating field**
  - 12 Shunt motor, nonreversing, without commutating field, two leads brought out**
  - 13 Shunt motor, nonreversing, without commutating field, three leads brought out**

**ML-STD-195**  
**20 October 1935**

**CONTENTS (Continued)**

<b>Figure</b>	
14	Shunt motor, reversing, without commutating field
15	Shunt motor, nonreversing, with commutating field, two leads brought out
16	Shunt motor, nonreversing, with commutating field, three leads brought out
17	Shunt motor, reversing, with commutating field
18	Series motor, nonreversing, without commutating field
19	Series motor, reversing, without commutating field
20	Series motor, nonreversing, with commutating field
21	Series motor, reversing, with commutating field
22	Series motor, reversing, without commutating field, split-series
23	Compound motor, nonreversing, without commutating field, two leads brought out
24	Compound motor, nonreversing, without commutating field, three leads brought out
25	Compound motor, reversing, without commutating field
26	Compound motor, nonreversing, with commutating field, two leads brought out
27	Compound motor, nonreversing, with commutating field, three leads brought out
28	Compound motor, reversing, with commutating field, five leads brought out
29	Compound motor, reversing, with commutating field, six leads brought out
30	Compound motor, reversing, with compensating and commutating fields, six leads brought out
31	Single-phase synchronous generator or motor
32	Single-phase, dual-voltage motor
33	Single-phase motor, reversible, split-phase, with automatic cut-out
34	Single-phase motor, nonreversible, split-phase, with automatic cut-out
35	Single-phase motor, reversible, split-phase, with manual cut-out
36	Single-phase capacitor-start capacitor-run motor and single-phase capacitor-start induction-run motor
37	Single-phase motor, reversible, split-phase, permanent capacitor
38	Single-phase motor, induction, with starter nonreversibility
39	Single-phase motor, series universal, nonreversing, without compensating fields
40	Single-phase motor, series universal, reversing, without compensating fields
41	Single-phase motor, series, with conductively compensated separate stator windings
42	Single-phase motor, series, reversible, with conductively compensated separate stator windings
43	Single-phase motor, series, with inductively compensated separate stator windings
44	Repulsion, repulsion-induction and repulsion-start induction run, all single-voltage and without compensating windings

**CONTENTS (Continued)**

<b>Figure</b>	
45	Repulsion, repulsion-induction and repulsion-start induction run, all double-voltage and without compensating windings
46	Repulsion, repulsion-induction and repulsion-start induction run, all single-voltage reversible
47	Repulsion motor, single voltage, inductively compensated
48	Repulsion motor, double voltage, inductively compensated
49	Diagram for two circuits per phase
50	Connection markings for two circuits per phase
51	Connection markings for two circuits in parallel per phase
52	Connection markings for two circuits in parallel per phase, permanently connected
53	Connection markings for series or parallel connections
54	Connection markings for delta-connected windings
55	Variable torque motor
56	Constant torque motor, arrangement 1
57	Constant torque motor, arrangement 2
58	Constant horsepower motor, arrangement 1
59	Constant horsepower motor, arrangement 2
60	Three-speed motor using three windings
61	Four-speed motor using two windings
62	Three-speed motor using two windings
63	Diagram for three circuits per phase
64	Connection markings for three circuits per phase
65	Connection markings for three circuits in parallel per phase — all circuit leads brought out
66	Connection markings for three circuits per phase connected in parallel inside the motor
67	Two-speed, two phase variable torque
68	Two-speed motor using two single-speed windings
69	Four-speed motor using two windings
70	Three-speed motor using two windings
71	Three-phase, wye-connected aircraft motor with six leads brought out
72	Three-phase, wye-connected aircraft motor with phases initially separated for dielectric tests
73	Three-phase, wye-connected aircraft motor
74	Standard two- and three-phase collector ring motor (usual connection wye)
75	Two- and three-phase collector ring induction motors, with two-phase rotor
76	Shunt-wound three-phase synchronous converter without commutating field
77	Shunt-wound three-phase synchronous converter with commutating field
78	Shunt-wound six-phase synchronous converter without commutating field
79	Shunt-wound six-phase synchronous converter with commutating field

**ML-5TD-195**  
**29 October 1968**

**CONTENTS (Continued)**

<b>Figure</b>	
80	Compound-wound six-phase synchronous converter without commutating field
81	Compound-wound six-phase synchronous converter with commutating field
82	Compound-wound three-phase synchronous converter without commutating field
83	Compound-wound three-phase synchronous converter with commutating field
84	Single-phase transformer, simple H and X windings with taps (subtractive polarity)
85	Single-phase transformer, simple H and X windings with taps (additive polarity)
86	Single-phase transformer, series multiple X winding without taps (subtractive polarity)
87	Single-phase transformer, series multiple X winding with taps (additive polarity)
88	Auto-transformer (subtractive polarity)
89	Single-phase transformer, three-wire series connection where neutral is brought out between other two leads (subtractive polarity)
90	Single-phase transformer, three-wire series connection where neutral is brought out between other two leads (additive polarity)
91	Single-phase transformer, two-wire parallel connection where neutral is brought out between other two leads (additive polarity)
92	Single-phase transformer, two-wire parallel connection where neutral is brought out between other two leads (subtractive polarity)
93	Single-phase transformer, two-wire series connection (subtractive polarity)
94	Single-phase transformer, two-wire series connection (additive polarity)
95	Single-phase transformer, two-wire parallel connection (subtractive polarity)
96	Single-phase transformer, two-wire parallel connection (additive polarity)
97	Single-phase transformer, 120-volt class connection (subtractive polarity)
98	Single-phase transformer, 120-volt class connection (additive polarity)
99	Single-phase transformer above 120-volt class connection (subtractive polarity)
100	Single-phase transformer, above 120-volt class connection (additive polarity)
101	Single-phase transformer, three-wire series connection transformer where neutral is brought out to side (subtractive polarity)

## CONTENTS (Continued)

Figure	
102	Single-phase transformer, three-wire series connection transformer where neutral is brought out to side (additive polarity)
103	Two-wire parallel connection transformer where neutral is brought out to side (subtractive polarity)
104	Two-wire parallel connection transformer where neutral is brought out to side (additive polarity)
105	Connections for transformers in parallel
106	Three-phase transformers without taps, angular displacement 0 degree
107	Three-phase transformers without taps, angular displacement 30 degrees
108	Three-phase transformers with taps, angular displacement 30 degrees
109	Angular displacement and connections-single-phase transformers connected delta-delta and wye-wye in three-phase banks with 0 degree angular displacement
110	Angular displacement and connections-single-phase transformers connected delta-wye and wye-delta in three-phase banks with 30 degrees angular displacement
111	Three-phase transformers connected delta-delta and wye-wye with 0 degree angular displacement
112	Three-phase transformers connected delta-wye and wye-delta with 30 degrees angular displacement
113	Auto-transformers
114	Six-phase transformers without taps, angular displacement 0 degree
115	Six-phase transformers without taps, angular displacement 30 degrees
116	Six-phase transformers with taps, angular displacement 30 degrees
117	Single-phase, full wave bridge type metallic rectifier stack assembly
118	Three-phase, full wave bridge type metallic rectifier stack assembly
119	Three-phase, four-wire, half wave type metallic rectifier stack assembly
120	Six-phase, full wave bridge type metallic rectifier stack assembly
121	Single-phase, full wave bridge type power supply with transformer
122	Three-phase, full wave bridge type power supply with transformer
123	Three-phase, full wave bridge type regulated, power supply with transformer

## TABLES

Table I. Marking nomenclature summary

## 1. SCOPE

**1.1 Scope.** — This standard covers uniform connection marking for the following equipment:

Direct-current generators.  
 Direct-current motors.  
 Alternating-current generators.  
 Alternating-current motors.  
 Synchronous converters.  
 Dynamotors.  
 Transformers, power.  
 Controllers.  
 Starters.  
 Brakes.  
 Metallic rectifier type power supplies.  
 Regulator sets, generator voltage.

This standard does not necessarily apply to the marking of connections used to interconnect the devices within the enclosure.

**1.2 Purpose.** — The purpose of this standard is to establish uniform connection marking for electric power assemblies. The standard, when used, will aid in making connections between the assemblies and other parts of the electric power system, and will prevent improper connections which may result in unsatisfactory operation or damage.

## 2. REFERENCED DOCUMENTS

**2.1** The following standard, of the issue in effect on date of invitation for bids, shall form a part of this standard.

### STANDARD

#### MILITARY

MIL-STD-104—Limits for Electrical Insulation Color.

## 3. DEFINITIONS

**3.1** Definitions (for the purpose of this standard).

**3.1.1 Assembly.** — An assembly is a num-

ber of parts or subassemblies, or both, combined to perform a specific function.

**3.1.2 Connection.** — Connection refers to terminal leads (with or without lug terminals), terminal boards, stud terminals, feed-through terminals, and bus bars which form a part of the assemblies specified in 1.1.

**3.1.3 Connection, negative.** — The negative connection is the one from which direct current enters a direct-current generator or the output side of a converter or from which direct current leaves a direct-current (d.c.) motor, input side of an inverter, d.c. field winding or other d.c. power consuming device. By this definition, the electron flow is from the commutator to negative brush in the case of a d.c. generator, from negative brush to commutator in the case of a d.c. motor, or from negative brush to collector ring in the case of a rotating field alternating-current a.c. generator or motor.

**3.1.4 Connection, positive.** — The positive connection is the one from which d.c. leaves a d.c. generator, rectifier or the output side of a converter and into which d.c. enters a d.c. motor, input side of an inverter, d.c. field winding or other d.c. power consuming device. By this definition, the electron flow is from the positive brush to the commutator in the case of a d.c. generator, from the commutator to the positive brush in the case of a d.c. motor, or from a collector ring to positive brush in the case of a rotating field a.c. generator or motor.

**3.1.5 Marking.** — Marking refers to letters, numbers, symbols, and colors applied to assemblies for identification or information.

**3.1.6 Phase sequence.** — For polyphase generating machines, phase sequence is the order in which the voltages successively reach their maximum positive values between connections.

**3.1.7 Standard direction of rotation.** — Unless otherwise required by the application



**MIL-STD-195**  
20 October 1955

machines shall be connected for standard direction of shaft rotation.

**Motors.** — The standard direction of shaft rotation for motors is counterclockwise when facing the end opposite the drive.

**Generators.** — The standard direction of shaft rotation for generators is clockwise when facing the end opposite the drive.

**2.1.7.1 Exceptions to standard direction of shaft rotation.** — Where more than two machines are mechanically coupled, this rule may not apply to all machines.

#### 4. GENERAL REQUIREMENTS

##### 4.1 Use of letters, numerals and symbols.

**4.1.1 General.** — The markings shall consist of the following forms or combinations of forms specified herein:

- (a) Sans-serif (Gothic) capital letter of the alphabet.
- (b) Arabic number used as a subscript to a letter.

(c) Symbol, usually arithmetical. The use of symbols is limited in this standard.

(d) Color coding, conforming to Standard MIL-STD-104 of the following types, for dynamotors and aircraft motors:<sup>1</sup>

(1) Solid colors.

(2) Tracer colors on a background of cream to white to light gray. Tracer width shall be varied to assist in distinguishing colors.

**4.2 Marking nomenclature.** — Markings shall conform to table I, which lists the functional part primarily associated with the connection to be marked. Table I also assigns forms, and representative subscripts or other appropriate marking, when applicable.

<sup>1</sup> This standard is not intended to establish color coding for cable supplying power to portable electric or electronic equipment, color coding for resistors, or color coding for electronic equipment.

TABLE I. Marking nomenclature summary

Functional part	Marking (examples)	Color code for dynamotors and aircraft motors <sup>1</sup>	
		Color code <sup>2</sup>	Width of tracer where used <sup>3</sup>
Alternating-current generators and motors	$\left\{ \begin{array}{l} T_1 \\ T_2 \\ T_3 \\ T_4 \\ T_5 \\ T_6 \\ T_7 \end{array} \right.$	Black	Narrow
		Red	Narrow
		Green	Wide
		Blue	Narrow
		Orange	Wide
		Brown	Wide
		White (cream to white to light gray)	.....
Bias winding connections (rectifier power supply)	$BC_1, BC_2, BC_3$	.....	.....
Brake	$B_1, B_2, B_3$	Brown	Wide
Brush on armature commutator	$\left\{ \begin{array}{l} A_1 \\ A_2 \\ A_3 \end{array} \right.$	White (cream to white to light gray)	.....
		$\left\{ \begin{array}{l} Black \\ Green \\ Blue \end{array} \right.$	Narrow
			Wide
.....	Narrow	.....	

**TABLE I. Marking nomenclature summary—Continued**

Functional part	Marking (examples)	Color code for dynamotors and shunt method	
		Color code	Width of taper where used
Brush on armature commutator connected internally to shunt field	$A_1F_1$ $A_2F_2$	White (creams to white to light gray) Black	Narrow
Brush on collector ring (except to d.c. field)	$M_1, M_2, M_3$	.....	.....
Control winding connection other than feedback and bias (rectifier power supply)	$OC_1, OC_2, OC_3$	.....	.....
Current feedback signal connections (rectifier power supply)	$CF_1, CF_2, CF_3$	.....	.....
Dynamotors:			
Single input (or lowest voltage):			
Positive	.....	White	Narrow
Negative	.....	Black	Narrow
Dual input (next higher voltage; if any):			
Positive	.....	Green	Narrow
Negative	.....	Brown	Narrow
Single output (or lowest voltage):			
Positive	.....	Red	Narrow
Negative	.....	Blue	Narrow
Dual output (second highest voltage):			
Positive	.....	Red	Green, narrow
Negative	.....	Green	Green, narrow
Triple output (highest voltage):			
Positive	.....	Red	Black, narrow
Negative	.....	Blue	Black, narrow
Equalizing lead	= (equality sign)	.....	.....
Field, commutating	$C_1, C_2$	.....	.....
Field, series	$S_1$ $S_2$	Red Black	Narrow Narrow
Field, shunt	$F_1$ $F_2$	Green Red	Wide Narrow
Field, series and shunt field connected internally	$S_2F_1$	Black	Narrow
Field, series, for engine starter generator	ST+, ST-	.....	.....
Line	$L_1, L_2, L_3$	Orange	Wide
Metallic rectifier stack assembly; a.c. input connections	$AC_1, AC_2, AC_3$	.....	.....
Neutral connections (except 3-wire generator)	Appropriate letter designation with subscript numeral 0	White (creams to white to light gray)	.....
Neutral connection from balance coil on 3-wire d.c. generator	±	.....	.....

**MIL-STD-195**  
29 October 1965

**TABLE I. Marking nomenclature summary—Continued**

Functional part	Marking (example)	Color code for dynamos and shunt motors <sup>1</sup>	
		Color code <sup>2</sup>	Width of lines where used <sup>3</sup>
Potential feedback signal connections (rectifier power supply)	PF <sub>1</sub> , PF <sub>2</sub> , PF <sub>3</sub>	-----	
Power supply, rectifier type, output connections	D <sub>1</sub> , D <sub>2</sub> , D <sub>3</sub>	-----	
Reactor for motor starting	Q, I, 2, 3	-----	
Resistor, armature and miscellaneous	R <sub>1</sub> , R <sub>2</sub> , R <sub>3</sub>	-----	
Resistor, dynamic braking	DR <sub>1</sub> , DR <sub>2</sub> , DR <sub>3</sub>	-----	
Resistor, shunt brake	BR <sub>1</sub> , BR <sub>2</sub> , BR <sub>3</sub>	-----	
Resistor, shunt field adjusting	V <sub>1</sub> , V <sub>2</sub> , V <sub>3</sub>	-----	
Transformer, power, auto, for motor starting	Mark in percent of full voltage. Example: 0, 50, 65, 80, 100	-----	-----
Transformer, power, winding No. 1 (single-phase/single-phase and 3-phase/3-phase, highest voltage winding and 3-phase/6-phase, 3-phase winding)	H <sub>1</sub> , H <sub>2</sub> , H <sub>3</sub>	-----	-----
Transformer, power, winding No. 2	X <sub>1</sub> , X <sub>2</sub> , X <sub>3</sub>	-----	-----
Transformer, power, winding No. 3	Y <sub>1</sub> , Y <sub>2</sub> , Y <sub>3</sub>	-----	-----
Transformer, power, winding No. 4	Z <sub>1</sub> , Z <sub>2</sub> , Z <sub>3</sub>	-----	-----

<sup>1</sup> Above/7 motors shall be identified as in section 3 or through the lead lengths by this code.

<sup>2</sup> Colors shall conform to Standard MIL-STD-194.

<sup>3</sup> Trace colors shall be on a background of cream to white to light gray.

**4.3 Method of permanently marking specific types of connections.**

**4.3.1 Terminal leads.** — In the case of terminal leads, the letters, numerals and symbols shall be etched, engraved, stamped or cast in (a) a fiber, metal or plastic piece which shall be securely attached to the lead or (b) that part of the lug terminal not intended to make electrical contact; metal pieces shall not be utilized to identify aircraft terminal leads.

**4.3.2 Terminal boards.** — In the case of terminal boards, the letters and numerals

shall be etched, engraved, stamped or cast in the terminal board adjacent to the terminal or in a terminal marking strip or designation plate adjacent to the terminals.

**4.3.3 Stud and feedthrough terminals.** — In the case of stud terminals or feedthrough terminals, the marking shall be etched, engraved, stamped or cast in the equipment adjacent to the terminal or in a terminal marking strip or designation plate adjacent to the terminals.

**4.3.4 Bus bars.** — In the case of bus bars, the marking shall be stamped in the bus bar

at a location which is near to, but not a part of, that area which is required to make the actual electrical connection. In addition, the marking shall be etched, engraved, stamped or cast in the enclosure or frame directly adjacent to the point of entry in an appropriate designation plate similarly located.

**4.4 Size of marking.** — The depth of letters, numbers and subscripts shall be not less than 0.003 inch. Exclusive of subscripts, the preferred size of each letter, number, and symbol shall be as follows:

**4.4.1 Terminal leads.** — The marking shall be not less than  $\frac{1}{16}$  inch in height when the outside diameter, including any insulation, of the terminal lead is  $\frac{1}{16}$  inch or less. The marking shall be not less than  $\frac{1}{8}$  inch in height, if lead diameter is greater than  $\frac{1}{16}$  inch.

**4.4.2 Terminal boards.** — The marking shall be not less than  $\frac{1}{16}$  inch in height when the outside diameter, including any insulation, of the internal leads connected to the board is  $\frac{1}{16}$  inch or less. The marking shall be not less than  $\frac{1}{8}$  inch when outside diameter of leads is larger than  $\frac{1}{16}$  inch.

**4.4.3 Stud and feedthrough terminals.** — The marking shall be not less than  $\frac{1}{16}$  inch in height when the diameter of the studs or terminals is  $\frac{1}{8}$  inch or less, when the diameter of the studs or terminals is larger, the markings shall be not less than  $\frac{1}{8}$  inch.

**4.4.4 Bus bars.** — The marking shall be not less than  $\frac{1}{8}$  inch in height or one-fourth the width of the bus bar, whichever is greater.

**4.5 Size and location of subscripts.** — Subscripts shall be at least half the height but not more than the full height of the basic letter which they follow. The position of the subscript shall be such that it is bisected by a horizontal line tangent to the base of the letter which the subscript follows:

#### 4.6 Use of subscript numerals.

**4.6.1 Subscript numerals on connections of d.c. machines and converters.** — The markings on the connections of a d.c. machine shall indicate the relation of circuits within machine. Subscript numerals shall be defined on the following basis:

- (a) The subscript numerals of connections of d.c. machines shall be selected so that with current direction in any single exciting winding from a lower to a higher subscript numeral, the generated voltage (counter electromotive force the case of a motor) in the direction of rotation from this excitation shall be positive for standard rotation, make the connection A, positive connection A, negative.
- (b) Markings of auxiliary excitation windings (such as series field, dual shunt fields) shall be selected so that the excitation of the auxiliary windings is cumulative with the current flow in the same direction, with respect to the subscript numerals, as the main field winding.
- (c) On d.c. machines, when an auxiliary lead passes through the mutator, compensating, or a field or any combination of fields before being brought out to connection to the external circuit, the connection marking of the lead shall be an A<sub>1</sub>, A<sub>2</sub>, A<sub>3</sub>, as applicable, provided all internal connections are permanently marked and that no leads (including leads to shunt fields) from junctions or combinations of these fields also brought out for connection to an external circuit. If leads from such junctions are brought out, the one used as an equalizer shall be marked with an equals sign, thus =, and all leads used as equalizers shall be marked

**AME-STD-195**  
**20 October 1955**

with the designation for the winding or windings to which the leads are connected.

- (d) When only one side of the shunt field is connected internally to an armature circuit lead, this armature circuit lead shall have a dual marking (A<sub>1</sub>F<sub>2</sub>, S<sub>1</sub>F<sub>2</sub>) indicating its armature circuit function and its shunt field function. Armature circuit leads need not have this dual markings on machines having both sides of the shunt field internally connected.

#### 4.6.2 Subscript numerals on connections of a.c. machines. —

4.6.2.1 In a.c. generators, the subscript numerals, indicate the order in which the voltages at the connections reach their maximum positive values (phase sequence) with standard rotation; hence for counterclockwise shaft rotation when facing the same end, the phase sequence will be 1, 3, 2.

4.6.2.2 In a synchronous converter, the sequence of the subscript numerals 1, 2, 3, 4, 5 and 6 applied to the collector ring connections M<sub>1</sub>, M<sub>2</sub>, M<sub>3</sub>, M<sub>4</sub>, M<sub>5</sub>, and M<sub>6</sub> indicates that when the transformer leads on which phase sequence is 1, 2, 3, 4, 5 and 6 are connected to correspondingly numbered collector ring connections on which the phase sequence is 1, 2, 3, 4, 5 and 6, the shaft rotation of the converter shall be clockwise when viewed from the d.c. or commutator end.

4.6.2.3 Subscript numerals on connections of polyphase induction motors. — In the case of polyphase single-speed motors equipped with integral terminal boxes, the subscript numerals on line terminals L<sub>1</sub>, L<sub>2</sub>, L<sub>3</sub>, shown in the table accompanying the three-phase motor diagrams, the phase sequence of the incoming power leads shall be indicated. When the leads are connected as shown in the table, the motor shall have the standard direction of rotation. For two-phase motors, regardless of the class of motor or the type

of winding, odd subscript numbers shall be in one phase and even subscript numbers shall be in the other phase.

## 5. DETAIL REQUIREMENTS

5.1 D. c. generators shall be marked according to figures 1 to 11 inclusive.

5.1.1 Two-wire (see figures 1 to 6 inclusive). — Direction of shaft rotation shall be standard. For differential connection of the series fields, no change shall be made on the field leads or connection markings on the machine, but the series field connection to the armature shall be shown reversed. (Commutating, compensating, and series field windings are shown on the A<sub>1</sub> side of the armature but this location although preferred, is not standardized). These windings may be connected on one side of the armature or may be divided part on either side.

5.1.2 Three-wire (see figures 7 to 11). — Direction of rotation shall be standard. When three collector rings are used they shall be marked M<sub>1</sub>, M<sub>2</sub>, and M<sub>3</sub>; two collector rings shall be marked M<sub>1</sub> and M<sub>2</sub>; one collector ring shall be marked M. For differential connection of the series fields, no change shall be made on the field leads or connection markings on the machine, but the connection of the series field to the armature shall be shown reversed.

5.1.3 Additional marking requirements. — When facing the end opposite the drive end and when reading from front (the end opposite drive) to back, right to left, or top to bottom, the connection markings shall be arranged in the following order for clockwise rotation: Positive (+), neutral, if provided (±), negative (-) for counterclockwise rotation: negative (-), neutral, if provided (±), and positive (+)

5.1.4 Gasoline or Diesel driven generators with series cranking winding. — Series wind-

ings shall be marked "ST" followed by the appropriate polarity marking.

**5.1.5 Rotary amplifiers.** — The markings shall conform to 5.1. The output lead leads shall be marked  $A_1$  (–) and  $A_2$  (+).

**5.2 D. c. motors** shall be marked in accordance with figures 12 to 30 inclusive.

**5.2.1 Shunt-wound** (see figures 12 to 17 inclusive). — Direction of shaft rotation for nonreversing motors shall be standard. Connections shown in these diagrams will give standard shaft rotation. (Commutating field windings are shown on the  $A_1$  side of the armature, but this location, although preferred, is not standardized.) This winding may be connected on one side of the armature or may be divided part on either side.

**5.2.2 Series-wound** (see figures 18 to 22). — Direction of shaft rotation for nonreversing motors shall be standard. Connections shown in these diagrams will give standard shaft rotation. (Commutating and series field windings are shown on the  $A_1$  side of the armature but this location, although preferred, is not standardized.) These windings may be connected on one side of the armature or may be divided part on either side.

**5.2.3 Compound-wound and stabilized shunt-wound** (see figures 23 to 30 inclusive). — Direction of shaft rotation for nonreversing motors shall be standard. Connections shown in these diagrams will give standard shaft rotation. (Compensating, commutating and series field windings are shown on the  $A_1$  side of the armature but this location, although preferred, is not standardized.) These windings may be connected on one side of the armature or may be divided part on either side. For differential connection of the series fields no change shall be made on the field leads or connection markings on the machine, but the connection of the series field to armature shall be shown reversed.

**5.3 A. c. generators and synchronous motors.**

**5.3.1 Three-two- and single-phase—** phase a.c. generator and synchronous a.c. windings shall have connection markings as described in 5.4.3 for three induction motors.

Two-phase a.c. generator and synchronous motor a.c. windings shall have connection markings as described in 5.4.6 for two-phase induction motors.

Single-phase a.c. generator and synchronous motor a.c. windings shall have connection markings as shown in figure 31.

The connection markings of d.c. windings shall be  $F_1$  and  $F_2$ .

**5.3.1.1 Additional requirements for phase generators.** — When facing the opposite the drive end, and when viewed from front (the end opposite drive) to right to left, or top to bottom, the connection markings shall be arranged in the following order for clockwise rotation:  $T_1$ ,  $T_2$  for rotating field generators and  $M_1$ ,  $M_2$  for rotating armature generators. For counterclockwise rotation:  $T_1$ ,  $T_2$ ,  $T_3$  for rotating field generators and  $M_1$ ,  $M_2$ ,  $M_3$  for rotating armature generators.

**5.3.2 A.c. single-phase motors** shall be marked in accordance with figures 31 inclusive.

**5.3.3 Dual-voltage motors.** — Regard the type of single-phase motor, whether series or parallel connection of any winding necessary, the following procedures shall be as shown on figure 32. Divide into two and  $T_1T_2$  shall be assigned to one half and  $T_3T_4$  to the other half of running winding.  $T_1T_2$  shall be assigned to one half and  $T_3T_4$  to the other half of starting or reversing winding.

**5.3.4 Single-voltage motors.** — The running winding shall be designated by  $T_1$ , the starting winding by  $T_2T_3$ . (This distinguishes it from a two-phase motor

**MB-STD-195**  
**29 October 1955**

ness odd subscript numbers in one-phase and even subscript numbers in the other phase.)

**5.4 Marking of a.c. polyphase induction motors shall be marked in accordance with figures 49 to 75 inclusive.**

**5.4.1 Classes of polyphase induction motors.** — Induction motors of the collector-ring or squirrel-cage type are divided into the following classes for determining connection markings:

**Class 1** — Three-phase motors having one synchronous speed. (See 5.4.3.)

**Class 2** — Three-phase motors having two synchronous speeds obtained from a reconnectible winding. (See 5.4.4.)

**Class 3** — Three-phase motors having two or more synchronous speeds obtained from two or more independent windings. (See 5.4.5.)

**Class 4** — Two-phase motors having one synchronous speed. (See 5.4.6.)

**Class 5** — Two-phase motors having two synchronous speeds obtained from a reconnectible winding. (See 5.4.7.)

**Class 6** — Two-phase motors having two or more synchronous speeds obtained from two or more independent windings. (See 5.4.8.)

**5.4.2 Purpose of rules applying to induction motors.** — Since the windings of a motor are seldom accessible, the markings of the connections are used to show the relations of the windings within the motor. A clockwise rotation in the sequence of connection numbering shall be used as described in subsequent paragraphs. For three-phase motors having two synchronous speeds obtained from a reconnectible winding, it is undesirable to adhere to the clockwise system of numbering for all connections, as this would cause the motor to run with clockwise shaft rotation on one speed and counterclockwise on the other speed if the power lines are connected to each set of connections in the

same sequence. For two-phase motors, regardless of the class of motor or the type of winding, the rules are such that odd subscript numbers are in one phase and even subscript numbers are in the other phase. The markings of all motors except those for two-speed motors using a single reconnectible winding, are based, as are the rules for three-phase windings, on a clockwise spiral system of rotation in the sequence of connection numbering.

**5.4.3 Class 1 induction motors.** — The following rules apply in determining the connection markings of any three-phase induction motor stator having only one synchronous speed regardless of how many circuits per phase there may be or how they are connected and they determine definitely which circuits belong in the same phase and also the polarity of the circuits.

**5.4.3.1 Wye-connected windings.**

- (a) A schematic vector diagram shall be drawn showing an inverted wye connection with the individual circuits in each phase arranged for series connection with correct polarity relation of circuits. The diagram for two circuits per phase, for example, shall be marked as shown on figure 49.
- (b) Starting with T, at the outside and top of the diagram, the ends of the circuits shall be numbered consecutively in a clockwise direction proceeding on a spiral towards the center of the diagram. For two circuits per phase, for example, the connections shall be marked as shown on figure 50.
- (c) A schematic diagram shall now be drawn showing the particular interconnection of circuits for the motor under consideration and the connection markings, as determined from the preceding paragraphs, shall be arranged to

give the correct polarity relation of circuits. If the winding on figure 5 is to be connected with two circuits in parallel per phase, the diagram and markings shall be as shown on figure 51.

- (d) The highest numbers shall be dropped and only the lowest number retained where two or more terminals are permanently connected together. If the winding on figure 51 is to have the two circuits in each phase permanently connected together with three line leads and three neutral leads brought out, the connection markings shall be as shown on figure 52. If the winding on figure 50 is to be arranged for either a series or a parallel connection, the diagram and connection markings shall be as shown on figure 53.

- (e) Where the ends of three coils are connected together to form a permanent neutral, the connection markings of the three leads so connected shall be dropped. If the neutral point is brought out it shall be marked  $T_n$ .

**5.4.3.2 Delta-connected windings.**—Where a winding is to be delta-connected, the inverted wye diagram shall be rotated 30 degrees counterclockwise as shown on figure 49.  $T_1$  shall be assigned to the outer end of the top leg and the numbering shall conform to item b under 5.4.3.1 and figure 50. There shall then be constructed, a schematic delta in which the  $T_1$  leg of the rotated wye becomes the right-hand side of the delta, the  $T_2$  leg becomes the bottom (horizontal) side and the  $T_3$  leg becomes the left side of the delta. Items c, d and e under 5.4.3.1 shall be applied as far as they are applicable to a delta connection as shown on figure 54.

**5.4.4 Class 2 induction motors.**—Inasmuch as part of the connections follow a clockwise

rotation and part a counterclockwise rotation in order to obtain the same direction of rotation for both speeds when the line leads are connected in the same sequence, it is difficult to give a written rule for connection markings. As a consequence, schematic diagrams for connection markings are shown for the few types of reconnectible windings on figures 48, 49, 50, 51, and 52.  $T_1$ ,  $T_2$ , and  $T_3$  are clockwise in all cases and are always the H connections for low speed. If a neutral is brought out it shall be marked  $T_n$ .

#### 5.4.5 Class 3 induction motors.

**5.4.5.1** If each independent winding gives only one synchronous speed, the winding giving the lowest speed shall take the same connection markings as determined in 5.4.3.1 for class 1 motors for the particular winding used. The connection markings for the higher speed windings shall be obtained by adding 10, 20, or 30, to the connection markings as determined in 5.4.3.1 for class 1 motors for the particular winding used, the sequence being determined by progressing each terminal to the next higher speed. Figure 61 is an example of the connection markings for a three-speed motor using three windings.

**5.4.5.2** If each independent winding is reconnectible to give two synchronous speeds

- (a) Diagrams of the windings to be used shall be drawn and each winding shall be given the connection markings shown in 5.4.3.1 for class 2 motors.
- (b) No further change shall be made to any of the connection markings of the winding giving the lowest speed, irrespective of whether the other speed obtained from the winding is an intermediate or the highest speed.
- (c) Ten shall be added to all connection markings of the winding giving the next higher speed, and an additional 10 is added to all connection markings for each



secutively higher speed winding. Figure 61 is an example of the connections markings for a four-speed motor using two windings.

**5.4.5.3** If two or more types of independent windings are used, part of which give only one synchronous speed and the rest give two synchronous speeds by reconnection:

- (a) Each winding shall be given the markings as determined in 5.4.3 for class 1, and 5.4.4 for class 2 motors, as the case may be.
- (b) No further change shall be made in any of the connection markings of the winding giving the lowest speed, irrespective of whether the other speeds obtained from this winding are an intermediate or the highest speed.
- (c) Ten shall be added to all connection markings of the winding giving the next higher speed and an additional 10 shall be added to all the connection markings of each consecutively higher speed winding. Figure 62 is an example of the connection markings for a three-speed motor using two windings.

**5.4.5.4** If, under any of the paragraphs of the rule for class 8 motors, the addition of 10, 20, or 30, to the basic connection markings causes a duplication of markings due to more than 9 leads being brought out on any one winding, then 20, 40, or 60, shall be added instead of 10, 20, or 30, to obtain the markings for the higher speeds.

**5.4.5.5** The figures shown for class 8 motors apply when stator connections of all windings are at the same end of the motor. Where one or more of the windings has stator connections at one end of the motor and part on the other end, the sequence of the connection markings for connections at one end may be shown on the diagram as shown on

the illustrative figures, and the connection markings for those brought out on the opposite end may be shown reversed in rotation. Where diagrams use this reversed rotation of markings, an explanatory note shall be included for the benefit of the controller of supplies in showing that when  $L_1$ ,  $L_2$ , and  $L_3$  are connected to any winding with the same sequence of subscript numbers ( $T_1$ ,  $T_2$ ,  $T_3$ , or  $T_{10}$ ,  $T_{20}$ ,  $T_{30}$  or  $T_{11}$ ,  $T_{12}$  or  $T_{13}$ ), the shaft rotation will be the same.

**5.4.6 Class 4 induction motors.**—The following rules may be applied to determine the connection marking of any two-phase induction motor stator having only one synchronous speed regardless of how many circuits per phase there may be or how they are connected and they determine definitely which circuits belong in the same phase, and also the polarity of the circuits. A schematic diagram shall be drawn with the individual circuits in each phase arranged for series connection with correct polarity relation of circuits as shown on figure 63. Starting with  $T_1$  at the outside and top of the diagram, the ends of the circuits shall be numbered consecutively in a clockwise direction proceeding on a spiral towards the center of the diagram. For three circuits per phase, for example, the connections shall be marked as shown on figure 64.

**5.4.6.1** A schematic diagram shall now be drawn showing the particular interconnection of circuits for the motor under consideration, and the connection markings as determined in the preceding paragraphs shall be arranged to give correct polarity relation of circuits. Where the winding on figure 64 is to be connected with three circuits in multiple per phase, the diagram and markings shall be as shown on figure 65.

**5.4.6.2** The highest numbers shall be dropped and only the lowest number retained where two or more connections are permanently connected. Where the winding on figure 65 is to have the three circuits in each phase permanently connected together with

a single line lead brought out from each end of each phase, the connection markings shall be as shown on figure 66.

5.4.6.3 Where a two-phase three-wire power supply is used, T<sub>1</sub> and T<sub>2</sub> shall be together and only the T<sub>1</sub> marking retained for the common wire.

5.4.6.4 Where the two phases are to be interconnected at the midpoint to connect to a two-phase five-wire system, the midpoint connection shall be marked T<sub>3</sub>.

5.4.7 *Class 5 induction motors (see figure 66)*<sup>1</sup>. — These windings do not readily lend themselves to the use of a written rule for determining their connection markings. Accordingly, each schematic diagram is shown with its markings. Connection markings for class 5 motors shall be as shown on figure 66.

#### 5.4.8 *Class 6 induction motors.*

5.4.8.1 Where each independent winding gives only one synchronous speed, the winding giving the lowest speed shall take the same connection markings as determined in 5.4.6, for class 4 motors for the particular winding used. The connection markings for the higher speed windings shall be obtained by adding 10, 20 or 30, to the connection markings determined by rule specified in 5.4.6 for class 4 motors for the particular winding used. The sequences shall be determined by progressing each time to the next higher speed. The connection markings for a two-speed motor using two single-speed winding shall be as shown on figure 68.

5.4.8.2 If each independent winding is reconnectible to give two synchronous speeds:

- (a) Vector diagrams of the windings to be used shall be drawn and each winding shall be given the markings shown in 5.4.7 for class 5 motors.

<sup>1</sup> Other diagrams for class 5 motors will be added as necessary.

- (b) No further change shall be made any of the markings of the winding giving the lowest speed, irrespective of whether the other speed obtained from this winding is an intermediate or the highest speed.

- (c) Ten shall be added to markings of the winding giving the next higher speed and an additional 10 shall be added to all the markings for each consecutively higher speed winding. Figure 69 is an example of the markings for four-speed motor using two windings.

5.4.8.3 If two or more types of independent windings are used, part of which give only one synchronous speed and the rest give two synchronous speeds by reconnection:

- (a) Each winding shall be given connection markings as determined in 5.4.6, for class 4 motors and 5.4.7, for class 5 motors, as the case may be.
- (b) No change shall be made in any of the connection markings of the winding giving the lowest speed, irrespective of whether the other speeds obtained from this winding are an intermediate or the highest speed.
- (c) Ten shall be added to all connection markings of the winding giving the next higher speed and additional 10 shall be added to the markings of each consecutively higher speed winding. Figure 70 is an example of connection markings for a three-speed motor using two windings.

5.4.8.4 If, under any of the sections of rule for class 6 motors, the addition of 10, or 20, to the basic connection markings causes a duplication of markings due to more than nine leads being brought out on

**MR-STD-195**  
**20 October 1933**

one winding, then 20, 40, or 60, shall be added instead of 10, 20, 30 to obtain the markings for the higher speeds.

**5.4.8.5 Connection markings — collector ring motors, two- and three-phase rotor connection.** — The markings shown on figures 74 and 75 shall apply.

**5.5 Synchronous converters and dynamotors.**

**5.5.1 Synchronous converters shall be marked as shown on figures 76 to 83 inclusive.** The direction of rotation shall be standard.

**5.5.2 Dynamotors shall be marked as shown in Table I.**

**5.6 Constant potential transformers shall be marked as shown on figures 84 to 104 inclusive.**

**5.6.1 Application of rules.** — These rules specify the markings of leads brought out of the enclosure but not the markings of winding connections inside the enclosure, except that these connections shall be marked with numbers in any manner which will permit convenient reference, and which cannot be confused with the markings of the leads brought out of the enclosures.

**5.6.2 Marking of connections and identification of windings.**

(a) In general, the windings of a transformer shall be distinguished by numbering No. 1, No. 2, No. 3. The highest voltage winding shall always be No. 1 except for three-phase to six-phase transformers. (See 5.6.1.) The sequence of winding numbers after No. 1 may be by voltage or by kilovolt-amperes.

(b) After the letters identifying leads have been assigned, the winding to which the respective leads are

connected then may be designated by that letter.

(c) A neutral lead of a three-phase transformer shall be marked with the proper letter followed by the zero subscript.

(d) *Exception.* — A lead brought out from the middle of the winding for some use other than that of a neutral lead (for example, a 50 percent starting tap) shall be marked as a tap lead.

**5.6.3 Diagrammatic sketch of connections.** — The manufacturer shall furnish with each transformer a complete diagram showing the leads and internal connections and their markings and the voltages obtainable with the various connections.

**5.6.4 Single-phase transformers.**

**5.6.4.1 Order of numbering leads in any winding.**

(a) The leads of any winding brought out of the enclosure shall be numbered for example, 1, 2, 3, 4, 5, the lowest and highest numbers marking the full winding and the immediate numbers marking fractions of winding or taps. Numbers shall be so applied that the potential difference from any lead having a lower number toward any lead having a higher number shall have the same sign at any instant, as specified in 5.7 and shown on figures 84, 85, 97 and 98.

(b) If a winding is divided into two or more parts for series parallel connections, and the leads of these parts are brought out of the enclosure, the above rule shall apply for the series connection with the addition that the leads of each portion of the winding shall be given consecutive numbers as

specified in 5.7 and shown on figures 89 and 90, for four or more leads brought out and figures 89, 90, 91, 92, 101 and 102 for two or three leads brought out.

- (c) When two leads are brought out of the enclosure through one bushing, the connections shall be marked in accordance with 5.7 and figures 97 and 98. When in addition a lead must be brought out from the midpoint, for three-wire operation the connections shall be identified in accordance with 5.7 and figures 101 and 102.

**5.6.4.2 Order of numbering leads of different windings.**

- (a) The numbering of the leads of the H winding and the leads of the X winding shall be applied so that when  $H_1$  and  $X_1$  are connected together and voltage applied to the transformer, the voltage between the highest numbered H lead and the highest numbered X lead shall be less than the voltage of the H winding.
- (b) When more than two windings are used, the same relationship shall apply between each pair of windings.

**5.6.4.3 Polarity.** — When leads are marked in accordance with the foregoing rules, the polarity of a transformer shall be:

- (a) Subtractive when  $H_1$  and  $X_1$  are adjacent in accordance with 5.7 and figure 108; also figures 84 and 86.
- (b) Additive when  $H_1$  is diagonally located with respect to  $X_1$ , in accordance with 5.7 and figures 85 and 97.
- (c) The same rule applies between the H and Y winding, and between the H and Z winding; for example,

when Y<sub>1</sub> or Z<sub>1</sub> is on the left side facing the Y or Z side of the case respectively, the polarity is subtractive, and additive if on the right.

**5.6.4.4 Location of H<sub>1</sub> lead.** — The connection on the right-hand side facing the high voltage side of the enclosure shall be designated  $H_1$ , and other H connections shall be designated in numerical order from right to left.

**5.6.4.5 Auto-transformer.** — Single-phase auto-transformer leads shall, so far as practicable, be marked in accordance with 1 requirements for subtractive polarity shown on figure 88.

**5.6.5 Three-phase transformers.**

**5.6.5.1 Marking of full winding leads.** The three leads for each winding which connect to the full phase windings shall be marked, for example,  $H_1, H_2, H_3, X_1, X_2, X_3, Y_1, Y_2, Y_3$ , respectively.

**5.6.5.2 Relation between highest voltage winding and other windings.**

- (a) The markings shall be so applied that if the phase sequence of voltage on the highest voltage winding is in the time order  $H_1, H_2, H_3$ , it will be in the time order for example,  $X_1, X_2, X_3$  and  $Y_1, Y_2, Y_3$  on the other winding.
- (b) In order that the markings of connections between phases of three-phase transformers indicate definite phase relationships they shall conform to one of three-phase groups as specified in 5.7.2 and shown on figures 107 and 108. The angular placement between the H winding and the X winding is the same angle in each of the voltage diagrams as specified in 5.7.2 shown on figures 106, 107

**ANSI-CFD-195**  
**29 October 1965**

108 between the lines passing from its neutral point through H<sub>1</sub> and X, respectively.

- (c) When more than one low voltage winding is used, the angular displacement between the H winding and each of the other low voltage windings is established in the same manner, using for example H<sub>1</sub> and Y<sub>1</sub>, H<sub>1</sub> and Z<sub>1</sub>, respectively.

#### **5.6.5.3 Tap leads.**

- (a) *General.* — Where tap leads, except neutral lead, are brought out of the enclosure, they shall be marked with the proper letter followed by the numbers 4, 7, for example, for one phase; 5, 8, for another phase; and 6, 9, for the third phase, as specified in 5.7.2 and shown on figure 108.
- (b) *Delta connection.* — The order of numbering tap leads shall be as follows: 4, 7, from lead 1 toward lead 2; 5, 8, from lead 2 toward lead 3; and 6, 9, from lead 3 toward lead 1 as specified in 5.7.2 and shown on figure 108.
- (c) *Wye connection.* — The order of numbering tap leads shall be as follows: 4, 7, from lead 1 toward neutral; 5, 8 from lead 2 toward neutral; and 6, 9, from lead 3 toward neutral, as specified in 5.7.2 and shown on figure 108.

#### **5.6.5.4 Interphase connection made outside of enclosure.**

- (a) Where the interphase connections are outside the enclosure, the leads shall be marked with the proper letter followed by the numbers for example, 1, 4, 7, 10, for one phase; 2, 5, 8, 11, for the second phase; and 3, 6, 9, 12, for the third phase.

- (b) The markings shall be so applied that when a wye connection is made by joining together the highest numbered leads of each phase all rules here given apply except item d of 5.6.2.

#### **5.6.5.5 Location of external leads.**

- (a) The H<sub>1</sub> lead shall be brought out on the right-hand side facing the highest voltage side of the enclosure. The H<sub>1</sub> and H<sub>2</sub> leads shall be brought out so that the three leads are arranged in numerical order reading from right to left when facing the highest voltage side of the enclosure (see 5.7.5). The H<sub>3</sub> lead, if present, will be located to the right of the H<sub>2</sub> lead when facing the highest voltage side of the enclosure.
- (b) The X<sub>1</sub> lead shall be brought out on the left-hand side of the enclosure facing the X winding side of the enclosure. The X<sub>1</sub> and X<sub>2</sub> leads shall be brought out so that the three leads are arranged in numerical order reading from left to right when facing the X winding side of the enclosure (see 5.7.5). The X<sub>3</sub> lead, if present, will be located to the left of the X<sub>2</sub> lead facing the X winding side of the enclosure.
- (c) The Y winding and Z winding leads, if present, shall be brought out and numbered in the same manner as the X winding leads.
- (d) The location of the external leads specified in items a, b, and c above shall apply to only one connection, such as a wye or a delta, of a given winding.
- (e) *Auto-transformer.* — Auto-transformer leads shall, so far as practicable, be marked in accordance with the corresponding multi-winding transformers, as speci-

ted in 5.7.5 and shown on figure 113.

### 5.6.6 Three-phase to six-phase transformers.

5.6.6.1 *Basis of rules.*—The rules for three-phase to six-phase transformers are set up on the basis that the three-phase winding is always the H winding.

5.6.6.2 *Marking of full winding leads.*—The three leads which connect to the three-phase winding shall be marked  $H_1$ ,  $H_2$ ,  $H_3$  and the six leads which connect to the full six-phase winding shall be marked  $X_1$ ,  $X_2$ ,  $X_3$ ,  $X_4$ ,  $X_5$ ,  $X_6$  as specified in 5.7.6 and shown on figures 114 to 116.

5.6.6.3 *Relation between three-phase and six-phase windings.*

(a) The markings shall be so applied that if the phase sequence of voltage on the three-phase connections is in the order  $H_1$ ,  $H_2$ ,  $H_3$ , it is in the time order  $X_1$ ,  $X_2$ ,  $X_3$ ,  $X_4$ ,  $X_5$ ,  $X_6$  on the six-phase connections.

(b) In order that the markings of connections between phases shall indicate definite phase relations, they shall conform to one of the four six-phase groups specified in 5.7.6 and shown on figures 114 and 115. The angular displacement between the three-phase and six-phase windings is the angle in each of the voltage vector diagrams between the lines passing from its neutral through  $H_1$  and  $X_1$ , respectively.

5.6.6.4 *Tap leads.*—Where tap leads from the six-phase windings are brought out of the case (neutral lead excepted), they shall be marked as follows:

(a) *Wye connection.*—Tap leads shall be marked from the two ends of each phase winding toward the middle or neutral point in the fol-

lowing order as specified in 5.7 and shown on figure 116:

$X_7$ ,  $X_{12}$  for example, from  $X_1$ ;  
 $X_8$ ,  $X_{13}$  for example, from  $X_2$ ;  
 $X_9$ ,  $X_{14}$  for example, from  $X_3$ ;  
 $X_{10}$ ,  $X_{15}$  for example, from  $X_4$ ;  
 $X_{11}$ ,  $X_{16}$  for example, from  $X_5$ ;  
 $X_{12}$ ,  $X_{17}$  for example, from  $X_6$ ;

A tap from the middle point any phase winding, not intended as a neutral, shall be given number determined by counting from  $X_1$ ,  $X_2$ , or  $X_3$  and not from  $X_4$ ,  $X_5$ , or  $X_6$ ; for example, if only taps brought out are 50 percent starting taps, they shall be numbered  $X_7$ ,  $X_8$ ,  $X_{11}$ .

(b) *Double delta connection.*—The leads shall be marked in the following order as specified in 5.7 and shown on figure 116:

$X_7$ ,  $X_{12}$  for example, from  $X_1$  toward  $X_2$ ;  
 $X_8$ ,  $X_{13}$  for example, from  $X_2$  toward  $X_3$ ;  
 $X_9$ ,  $X_{14}$  for example, from  $X_3$  toward  $X_4$ ;  
 $X_{10}$ ,  $X_{15}$  for example, from  $X_4$  toward  $X_5$ ;  
 $X_{11}$ ,  $X_{16}$  for example, from  $X_5$  toward  $X_6$ ;  
 $X_{12}$ ,  $X_{17}$  for example, from  $X_6$  toward  $X_1$ .

5.7 Connection diagrams and lead markings for single-phase transformers. — The rules for lead markings to transformers having subtractive and additive polarity shall be as shown on figures 84 to 104 inclusive. (The ground connection shown in broken lines applies to single-phase installations only.)

5.7.1 *Polarity and connections — single-phase transformers.* — The connection of single-phase transformers of additive polarity, subtractive polarity, and combination of additive and subtractive polarity shall be as shown on figure 105.

5.7.2 *Lead markings and voltage vector diagrams — three-phase transformer connections.* — The method of marking transformer leads which are brought out of the enclosure shall be as shown on figures 106 to 108 inclusive.

**MIL-STD-195**  
**29 October 1963**

**5.7.3 Angular displacement and connections — single-phase transformers connected delta-delta and Y-Y in three-phase banks with 0 degree angular displacement.** — Connections of single-phase transformers of additive polarity, subtractive polarity, and combinations of additive and subtractive polarity in banks shall be as shown on the figures under 109.

**5.7.4 Angular displacement and connections — single-phase transformers connected delta-Y and Y-delta in three-phase banks with 30 degree angular displacement.** — Connections of single-phase transformers of additive polarity, subtractive polarity, and combinations of additive and subtractive polarity in banks shall be as shown on figures under 112.

**5.7.5 Angular displacement and lead markings for three-phase transformers.** — These connections shall be as shown on figures 111, 112 and 113.

**5.7.6 Lead markings and voltage vector diagrams—usual six-phase transformer connections.** — The method of marking transformer leads brought out of the enclosure shall be as shown on figures 114 to 116 inclusive.

**5.8 Motor starters and controllers.**

**5.8.1 External connections.** — External connections shall be marked as indicated:

**Line - A.c. - Single-phase:**  $L_1, L_2$   
**3-phase:**  $L_1, L_2, L_3$   
**3-phase, 3-wire:**  $L_1, L_2, L_3$   
 ( $L_3$  to be the common line.)  
**3-phase, 4-wire:**  $L_1, L_2, L_3, L_4$   
 ( $L_1, L_2$  = phase 1;  
 $L_3, L_4$  = phase 2.)  
**D.c. -  $L_1 - L_2$**   
 (Plus and minus signs may be added when desirable to indicate polarity, or distinguish from a.c. circuits.)

**5.8.2 Rotating equipment.** — Unless otherwise specified herein, connections to rotating equipment shall be marked the same as the rotating equipment based on standard direction of rotation.

D.c. generators .....	See 5.1
D.c. motors .....	See 5.2
A.c. generators and synchronous motors .....	See 5.3
A.c. single-phase motors .....	See 5.3.1
A.c. polyphase motors .....	See 5.4
A.c. synchronous converters and dynamotors .....	See 5.5

**5.8.3 Transformers.** — Connections to transformers shall be marked the same as the transformers.

(a) **Constant potential transformers.** — (See 5.6.)

(b) **Autotransformers for motor starters.** — The taps and the coils of autotransformer motor starters shall be marked as follows: The end of the winding which is connected to the wye or delta point, and which is the start of the winding shall be marked 0. The intermediate taps shall be marked with the approximate percentage of line voltage that will be delivered under the load condition as specified. The end connection, which goes to the line, shall be marked 100. (Example: 0-50-65-80-100.)

**5.8.4 Reactors.** — The start of the winding shall be marked 0, and the taps shall be marked for example, 1, 2, 3, 4. The identification plate, or terminal board, shall show the connection to be used for each of the specified voltages.

**5.8.5 Resistors.** — The connection markings for resistors shall be as follows:

Armature and miscellaneous.....	R <sub>1</sub> , R <sub>2</sub> , R <sub>3</sub>
Shunt field adjusting:	
Fixed resistors with taps.....	V <sub>1</sub> , V <sub>2</sub> , V <sub>3</sub>
Adjustable resistors (rheostatic) V <sub>1</sub> , V <sub>2</sub>	
Shunt brake.....	BR <sub>1</sub> , BR <sub>2</sub> , BR <sub>3</sub>
Dynamic braking only.....	DR <sub>1</sub> , DR <sub>2</sub> , DR <sub>3</sub>
End connections.....	When a resistor is made of two or more units and it is necessary to connect these units, the use of the letters A to A, B to B, is recommended.

**5.8.6 Brakes.** — Connection markings for brakes shall be as follows: B<sub>1</sub>, B<sub>2</sub>, B<sub>3</sub>.

**5.8.7 Control circuit.** — Numbers shall be used to indicate and identify the connections on controllers for external control circuits.

**5.9 Power supplies metallic rectifier.**

**5.9.1 Metallic rectifier power supplies** shall be marked as shown on figures 117 to 128 inclusive.

**5.9.1.1 Power input connections of a metallic rectifier type power supply equipment** which are intended for connection to the primary line source of a.c. power (a.c. line) shall be marked as follows:

1 phase (two-wire).....	L <sub>1</sub> , L <sub>2</sub>
1 phase (three-wire, center tap).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub> (L <sub>3</sub> = center tap.)
3 phase (three-wire).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub>
3 phase (four-wire).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub> , L <sub>4</sub> (L <sub>4</sub> = neutral.)

**5.9.1.2 Input connections of a metallic rectifier stack assembly** forming a separately mounted or demountable unit of a rectifier power supply, which are not intended for connection directly to the a.c. line shall be marked as specified herein.

**5.9.1.2.1 Connections to be made to a single power supply transformer** shall be marked the same as the corresponding output connection of the transformer.

**5.9.1.2.2 Connections to be made to more than one separately assembled and mounted transformers** shall be marked the same as the corresponding connections of the transformers with the addition of a letter in parentheses identifying the particular transformer. For example:

	Connection marking metallic rectifier stack assembly
Transformer (A)	
Connection X <sub>1</sub>	X <sub>1</sub> (A)
Connection X <sub>2</sub>	X <sub>2</sub> (A)
Connection X <sub>3</sub>	X <sub>3</sub> (A)
Transformer (B)	
Connection X <sub>1</sub>	X <sub>1</sub> (B)
Connection X <sub>2</sub>	X <sub>2</sub> (B)
Connection X <sub>3</sub>	X <sub>3</sub> (B)

**5.9.1.2.3 Connections to be made directly to the output connections of an a.c. generator (or other rotating machine furnishing alternating current to be rectified)** with use of an intermediate disconnect device shall be marked the same as the corresponding connections of the a.c. machine.

**5.9.1.2.4 Connections to be made other than to units as described in 5.9.1.2.1 to 5.9.1.2.3**



**ME-STD-195**  
**20 October 1968**

inclusive shall be marked as follows:

1 phase (two-wire).....	AC <sub>1</sub> , AC <sub>2</sub>
1 phase (three-wire, center tap).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>0</sub> (AC <sub>1</sub> = center tap.)
3 phase (three-wire).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub>
3 phase (four-wire).....	AC <sub>0</sub> , AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> (AC <sub>0</sub> = neutral.)
6 phase (six-wire).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> , AC <sub>4</sub> , AC <sub>5</sub> , AC <sub>6</sub>
6 phase (seven-wire).....	AC <sub>0</sub> , AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> , AC <sub>4</sub> , AC <sub>5</sub> , AC <sub>6</sub> (AC <sub>0</sub> = neutral.)

5.9.1.3 Power output connections of a metallic rectifier type power supply equipment which are intended for connection directly to a specific equipment, such as a d.c. motor or the field of an a.c. generator, shall be marked the same as the corresponding input connections of the connected equipment.

5.9.1.4 Power output connections of a rectifier type power supply equipment which are not intended for connection to a specific equipment or which may furnish d.c. power to a variety of equipments or devices shall be marked D<sub>1</sub>, D<sub>2</sub>, D<sub>3</sub>, and so on. D<sub>1</sub> shall apply to the DC negative lead and D<sub>2</sub> shall apply to the DC positive lead. Equalizing connections shall be marked with an equality sign (=).

5.9.1.5 Output connections of a separately mounted or demountable unit of a rectifier type power supply which is to be connected between the primary power source and the rectifier stack assembly and which is not one of the units referred to in 5.9.1.2.1 to 5.9.1.2.8 inclusive shall be marked the same as the corresponding rectifier stack assembly input connections.

#### 5.9.1.6 Subscript numerals.

Input side, or polyphase inputs, the subscript numerals 1, 2, 3 and so on shall indicate the order in which the voltages at the connections reach their maximum positive values (phase sequence).

Output side. — The marking shall be so applied that the lowest subscript is applied to the negative connection and the highest subscripts shall then be applied to any intermediate taps such that the subscript numbers increase consecutively in the order of increase in potential of the connections. If

there is more than one independent d.c. output, the one of lowest power rating shall be marked as indicated herein. The other outputs shall be marked similarly except that 10, 20, 30 and so on, shall be used as the subscript numbers, when determined as shown herein, in the order of increasing power output.

Control connections. — The markings of the control connections shall correspond to the above output markings.

5.10 Regulator sets, generator voltage. — Unless otherwise specified herein, connections to generators, including field windings, shall be marked the same as the leads of the generators based on standard direction of rotation:

D.c. generators.....	(See 5.1.)
A.c. generators.....	(See 5.1.)
Rotary amplifiers.....	(See 5.1.)

Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring agency or as directed by the contracting officer.

Copies of this standard for Military use may be obtained as indicated in the foreword to the Index of Military Specifications and Standards.

Copies of this standard may be obtained for other than official use by individuals, firms, and contractors from the Superintendent of Documents, U. S. Government Printing Office, Washington 25, D. C.

Both the title and identifying symbol number should be stipulated when requesting copies of Military standards.

#### Comments:

Army—Corps of Engineers  
 Navy—Bureau of Ships  
 Air Force

#### Other Interest:

Army—HQDA&T  
 Navy—ASDC&Y

specified in 5.7 and shown on figures 89 and 90, for four or more leads brought out and figures 89, 90, 91, 92, 101 and 102 for two or three leads brought out.

- (c) When two leads are brought out of the enclosure through one bushing, the connections shall be marked in accordance with 5.7 and figures 97 and 98. When in addition a lead must be brought out from the midpoint, for three-wire operation the connections shall be identified in accordance with 5.7 and figures 101 and 102.

**5.6.4.2 Order of numbering leads of different windings.**

- (a) The numbering of the leads of the H winding and the leads of the X winding shall be applied so that when  $H_1$  and  $X_1$  are connected together and voltage applied to the transformer, the voltage between the highest numbered H lead and the highest numbered X lead shall be less than the voltage of the H winding.
- (b) When more than two windings are used, the same relationship shall apply between each pair of windings.

**5.6.4.3 Polarity.** — When leads are marked in accordance with the foregoing rules, the polarity of a transformer shall be:

- (a) Subtractive when  $H_1$  and  $X_1$  are adjacent in accordance with 5.7 and figure 108; also figures 84 and 86.
- (b) Additive when  $H_1$  is diagonally located with respect to  $X_1$ , in accordance with 5.7 and figures 85 and 97.
- (c) The same rule applies between the H and Y winding, and between the H and Z winding; for example,

when Y, or Z, is on the left side facing the Y or Z side of the case respectively, the polarity is subtractive, and additive if on the right.

**5.6.4.4 Location of  $H_1$  lead.** — The connection on the right-hand side facing the highest voltage side of the enclosure shall be designated  $H_1$ , and other H connections shall be designated in numerical order from right to left.

**5.6.4.5 Auto-transformer.** — Single-phase auto-transformer leads shall, so far as practicable, be marked in accordance with the requirements for subtractive polarity shown on figure 88.

**5.6.5 Three-phase transformers.**

**5.6.5.1 Marking of full winding leads.** The three leads for each winding which connect to the full phase windings shall be marked, for example,  $H_1, H_2, H_3, X_1, X_2, X_3, Y_1, Y_2, Y_3$ , respectively.

**5.6.5.2 Relation between highest voltage winding and other windings.**

- (a) The markings shall be so applied that if the phase sequence of voltage on the highest voltage winding is in the time order  $H_1, H_2, H_3$ , it will be in the time order for example,  $X_1, X_2, X_3$  and  $Y_1, Y_2, Y_3$  on the other windings.
- (b) In order that the markings of connections between phases of three-phase transformers shall indicate definite phase relationships they shall conform to one of three-phase groups as specified in 5.7.2 and shown on figures 107 and 108. The angular placement between the H winding and the X winding in each of the voltage diagrams as specified in 5.7.1 is shown on figures 106, 107

**ANSI-STD-195**  
**20 October 1965**

108 between the lines passing from its neutral point through H<sub>1</sub> and X, respectively.

- (c) When more than one low voltage winding is used, the angular displacement between the H winding and each of the other low voltage windings is established in the same manner, using for example H<sub>1</sub> and Y<sub>1</sub>, H<sub>1</sub> and Z<sub>1</sub>, respectively.

#### 5.6.5.3 *Tap leads.*

- (a) *General.* — Where tap leads, except neutral lead, are brought out of the enclosure, they shall be marked with the proper letter followed by the numbers 4, 7, for example, for one phase; 5, 8, for another phase; and 6, 9, for the third phase, as specified in 5.7.2 and shown on figure 108.
- (b) *Delta connection.* — The order of numbering tap leads shall be as follows: 4, 7, from lead 1 toward lead 2; 5, 8, from lead 2 toward lead 3; and 6, 9, from lead 3 toward lead 1 as specified in 5.7.2 and shown on figure 108.
- (c) *Wye connection.* — The order of numbering tap leads shall be as follows: 4, 7, from lead 1 toward neutral; 5, 8 from lead 2 toward neutral; and 6, 9, from lead 3 toward neutral, as specified in 5.7.2 and shown on figure 108.

#### 5.6.5.4 *Interphase connection made outside of enclosure.*

- (a) Where the interphase connections are outside the enclosure, the leads shall be marked with the proper letter followed by the numbers for example, 1, 4, 7, 10, for one phase; 2, 5, 8, 11, for the second phase; and 3, 6, 9, 12, for the third phase.

- (b) The markings shall be so applied that when a wye connection is made by joining together the highest numbered leads of each phase all rules here given apply except item d of 5.6.2.

#### 5.6.5.5 *Location of external leads.*

- (a) The H<sub>1</sub> lead shall be brought out on the right-hand side facing the highest voltage side of the enclosure. The H<sub>2</sub> and H<sub>3</sub> leads shall be brought out so that the three leads are arranged in numerical order reading from right to left when facing the highest voltage side of the enclosure (see 5.7.5). The H<sub>0</sub> lead, if present, will be located to the right of the H<sub>1</sub> lead when facing the highest voltage side of the enclosure.
- (b) The X<sub>1</sub> lead shall be brought out on the left-hand side of the enclosure facing the X winding side of the enclosure. The X<sub>2</sub> and X<sub>3</sub> leads shall be brought out so that the three leads are arranged in numerical order reading from left to right when facing the X winding side of the enclosure (see 5.7.5). The X<sub>0</sub> lead, if present, will be located to the left of the X<sub>1</sub> lead facing the X winding side of the enclosure.
- (c) The Y winding and Z winding leads, if present, shall be brought out and numbered in the same manner as the X winding leads.
- (d) The location of the external leads specified in items a, b, and c above shall apply to only one connection, such as a wye or a delta, of a given winding.
- (e) *Auto-transformer.* — Auto-transformer leads shall, so far as practicable, be marked in accordance with the corresponding multi-winding transformers, as speci-

defined in 5.7.5 and shown on figure 113.

### 5.6.6 Three-phase to six-phase transformers.

5.6.6.1 *Basis of rules.*—The rules for three-phase to six-phase transformers are set up on the basis that the three-phase winding is always the H winding.

5.6.6.2 *Marking of full winding leads.*—The three leads which connect to the three-phase winding shall be marked  $H_1$ ,  $H_2$ ,  $H_3$  and the six leads which connect to the full six-phase winding shall be marked  $X_1$ ,  $X_2$ ,  $X_3$ ,  $X_4$ ,  $X_5$ ,  $X_6$  as specified in 5.7.6 and shown on figures 114 to 116.

5.6.6.3 *Relation between three-phase and six-phase windings.*

(a) The markings shall be so applied that if the phase sequence of voltage on the three-phase connections is in the order  $H_1$ ,  $H_2$ ,  $H_3$ , it is in the time order  $X_1$ ,  $X_2$ ,  $X_3$ ,  $X_4$ ,  $X_5$ ,  $X_6$  on the six-phase connections.

(b) In order that the markings of connections between phases shall indicate definite phase relations, they shall conform to one of the four six-phase groups specified in 5.7.6 and shown on figures 114 and 115. The angular displacement between the three-phase and six-phase windings is the angle in each of the voltage vector diagrams between the lines passing from its neutral through  $H_1$  and  $X_1$ , respectively.

5.6.6.4 *Tap leads.*—Where tap leads from the six-phase windings are brought out of the case (neutral lead excepted), they shall be marked as follows:

(a) *Wye connection.*—Tap leads shall be marked from the two ends of each phase winding toward the middle or neutral point in the fol-

lowing order as specified in 5.7.6 and shown on figure 116:

$X_7$ ,  $X_{12}$  for example, from  $X_1$ ;  
 $X_8$ ,  $X_{13}$  for example, from  $X_2$ ;  
 $X_9$ ,  $X_{14}$  for example, from  $X_3$ ;  
 $X_{10}$ ,  $X_{15}$  for example, from  $X_4$ ;  
 $X_{11}$ ,  $X_{16}$  for example, from  $X_5$ ;  
 $X_{12}$ ,  $X_{17}$  for example, from  $X_6$ .

A tap from the middle point of any phase winding, not intended as a neutral, shall be given number determined by counting from  $X_7$ ,  $X_8$ , or  $X_9$  and not from  $X_1$ ,  $X_2$ , or  $X_3$ ; for example, if only taps brought out are 50 percent starting taps, they shall be numbered  $X_7$ ,  $X_8$ ,  $X_{11}$ .

(b) *Double delta connection.*—Tap leads shall be marked in the following order as specified in 5.7.6 and shown on figure 116:

$X_7$ ,  $X_{12}$  for example, from  $X_1$  toward  $X_2$ ;  
 $X_8$ ,  $X_{13}$  for example, from  $X_2$  toward  $X_3$ ;  
 $X_9$ ,  $X_{14}$  for example, from  $X_3$  toward  $X_4$ ;  
 $X_{10}$ ,  $X_{15}$  for example, from  $X_4$  toward  $X_5$ ;  
 $X_{11}$ ,  $X_{16}$  for example, from  $X_5$  toward  $X_6$ ;  
 $X_{12}$ ,  $X_{17}$  for example, from  $X_6$  toward  $X_1$ .

5.7 Connection diagrams and lead markings—single-phase transformers.—The rules for lead markings to transformers having subtractive and additive polarity shall be as shown on figures 84 to 104 inclusive. (The ground connection shown in broken lines applies to single-phase installations only.)

5.7.1 *Polarity and connections—single-phase transformers.*—The connection of single-phase transformers of additive polarity, subtractive polarity, and combination of additive and subtractive polarity shall be as shown on figure 106.

5.7.2 *Lead markings and voltage vector diagrams—three-phase transformer connections.*—The method of marking transformer leads which are brought out of the enclosure shall be as shown on figures 106 to 108 inclusive.

**IEEE-STD-195**  
**20 October 1983**

**5.7.3 Angular displacement and connections — single-phase transformers connected delta-delta and Y-Y in three-phase banks with 0 degree angular displacement.** — Connections of single-phase transformers of additive polarity, subtractive polarity, and combinations of additive and subtractive polarity in banks shall be as shown on the figures under 100.

**5.7.4 Angular displacement and connections — single-phase transformers connected delta-Y and Y-delta in three-phase banks with 30 degree angular displacement.** — Connections of single-phase transformers of additive polarity, subtractive polarity, and combinations of additive and subtractive polarity in banks shall be as shown on figures under 112.

**5.7.5 Angular displacement and lead markings for three-phase transformers.** — These connections shall be as shown on figures 111, 112 and 113.

**5.7.6 Lead markings and voltage vector diagrams—usual six-phase transformer connections.** — The method of marking transformer leads brought out of the enclosure shall be as shown on figures 114 to 116 inclusive.

## 5.8 Motor starters and controllers.

**5.8.1 External connections.** — External connections shall be marked as indicated:

**Line - A.c. - Single-phase:**  $L_1, L_2$   
**3-phase:**  $L_1, L_2, L_3$   
**3-phase, 3-wire:**  $L_1, L_2, L_3$   
 ( $L_3$  to be the common line.)  
**3-phase, 4-wire:**  $L_1, L_2, L_3, L_4$   
 ( $L_1, L_2$  = phase 1;  
 $L_3, L_4$  = phase 2.)  
**D.c. -  $L_1 - L_2$**   
 (Plus and minus signs may be added when desirable to indicate polarity, or distinguish from a.c. circuits.)

**5.8.2 Rotating equipment.** — Unless otherwise specified herein, connections to rotating equipment shall be marked the same as the rotating equipment based on standard direction of rotation.

D.c. generators .....	See 5.1
D.c. motors .....	See 5.2
A.c. generators and synchronous motors .....	See 5.3
A.c. single-phase motors .....	See 5.3.2
A.c. polyphase motors .....	See 5.4
A.c. synchronous converters and dynamos .....	See 5.5

**5.8.3 Transformers.** — Connections to transformers shall be marked the same as the transformers.

(a) **Constant potential transformers.** — (See 5.6.)

(b) **Autotransformers for motor starters.** — The taps and the coils of autotransformer motor starters shall be marked as follows: The end of the winding which is connected to the wye or delta point, and which is the start of the winding shall be marked 0. The intermediate taps shall be marked with the approximate percentage of line voltage that will be delivered under the load condition as specified. The end connection, which goes to the line, shall be marked 100. (Example: 0-50-65-80-100.)

**5.8.4 Reactors.** — The start of the winding shall be marked 0, and the taps shall be marked for example, 1, 2, 3, 4. The identification plate, or terminal board, shall show the connection to be used for each of the specified voltages.

**5.8.5 Resistors.** — The connection markings for resistors shall be as follows:

Armature and miscellaneous.....	R <sub>1</sub> , R <sub>2</sub> , R <sub>3</sub>
Shunt field adjusting:	
Fixed resistors with taps.....	V <sub>1</sub> , V <sub>2</sub> , V <sub>3</sub>
Adjustable resistors (rheostatic) V <sub>1</sub> , V <sub>2</sub>	
Shunt brake.....	BR <sub>1</sub> , BR <sub>2</sub> , BR <sub>3</sub>
Dynamic braking only.....	DR <sub>1</sub> , DR <sub>2</sub> , DR <sub>3</sub>
End connections.....	When a resistor is made of two or more units and it is necessary to connect these units, the use of the letters A to A, B to B, is recommended.

**5.8.6 Brakes.** — Connection markings for brakes shall be as follows: B<sub>1</sub>, B<sub>2</sub>, B<sub>3</sub>.

**5.8.7 Control circuit.** — Numbers shall be used to indicate and identify the connections on controllers for external control circuits.

### 5.9 Power supplies metallic rectifier.

**5.9.1 Metallic rectifier power supplies** shall be marked as shown on figures 117 to 123 inclusive.

**5.9.1.1 Power input connections of a metallic rectifier type power supply equipment** which are intended for connection to the primary line source of a.c. power (a.c. line) shall be marked as follows:

1 phase (two-wire).....	L <sub>1</sub> , L <sub>2</sub>
1 phase (three-wire, center tap).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub> (L <sub>3</sub> = center tap.)
3 phase (three-wire).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub>
3 phase (four-wire).....	L <sub>1</sub> , L <sub>2</sub> , L <sub>3</sub> , L <sub>4</sub> (L <sub>4</sub> = neutral.)

**5.9.1.2 Input connections of a metallic rectifier stack assembly** forming a separately mounted or demountable unit of a rectifier power supply, which are not intended for connection directly to the a.c. line shall be marked as specified herein.

**5.9.1.2.1 Connections to be made to a single power supply transformer** shall be marked the same as the corresponding output connection of the transformer.

**5.9.1.2.2 Connections to be made to more than one separately assembled and mounted transformers** shall be marked the same as the corresponding connections of the transformers with the addition of a letter in parentheses identifying the particular transformer. For example:

	Connection marking metallic rectifier stack assembly
Transformer (A)	
Connection X <sub>1</sub>	X <sub>1</sub> (A)
Connection X <sub>2</sub>	X <sub>2</sub> (A)
Connection X <sub>3</sub>	X <sub>3</sub> (A)
Transformer (B)	
Connection X <sub>1</sub>	X <sub>1</sub> (B)
Connection X <sub>2</sub>	X <sub>2</sub> (B)
Connection X <sub>3</sub>	X <sub>3</sub> (B)

**5.9.1.2.3 Connections to be made direct to the output connections of an a.c. generator (or other rotating machine furnishing alternating current to be rectified)** with use of an intermediate disconnect shall be marked the same as the corresponding connections of the a.c. machine.

**5.9.1.2.4 Connections to be made other than to units as described in 5.9.1.2.1 to 5.9.1.2.3**

**MIL-STD-195**  
**20 October 1963**

Inclusive shall be marked as follows:

1 phase (two-wire).....	AC <sub>1</sub> , AC <sub>2</sub>
1 phase (three-wire, center tap).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> (AC <sub>3</sub> = center tap.)
3 phase (three-wire).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub>
3 phase (four-wire).....	AC <sub>0</sub> , AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> (AC <sub>0</sub> = neutral.)
6 phase (six-wire).....	AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> , AC <sub>4</sub> , AC <sub>5</sub> , AC <sub>6</sub>
6 phase (seven-wire).....	AC <sub>0</sub> , AC <sub>1</sub> , AC <sub>2</sub> , AC <sub>3</sub> , AC <sub>4</sub> , AC <sub>5</sub> , AC <sub>6</sub> (AC <sub>0</sub> = neutral.)

5.9.1.3 Power output connections of a metallic rectifier type power supply equipment which are intended for connection directly to a specific equipment, such as a d.c. motor or the field of an a.c. generator, shall be marked the same as the corresponding input connections of the connected equipment.

5.9.1.4 Power output connections of a rectifier type power supply equipment which are not intended for connection to a specific equipment or which may furnish d.c. power to a variety of equipments or devices shall be marked D<sub>1</sub>, D<sub>2</sub>, D<sub>3</sub>, and so on. D<sub>1</sub> shall apply to the DC negative lead and D<sub>2</sub> shall apply to the DC positive lead. Equalizing connections shall be marked with an equality sign (=).

5.9.1.5 Output connections of a separately mounted or demountable unit of a rectifier type power supply which is to be connected between the primary power source and the rectifier stack assembly and which is not one of the units referred to in 5.9.1.2.1 to 5.9.1.2.8 inclusive shall be marked the same as the corresponding rectifier stack assembly input connections.

#### 5.9.1.6 Subscript numerals.

Input side, or polyphase inputs, the subscript numerals 1, 2, 3 and so on shall indicate the order in which the voltages at the connections reach their maximum positive values (phase sequence).

Output side. — The marking shall be so applied that the lowest subscript is applied to the negative connection and the highest subscripts shall then be applied to any intermediate taps such that the subscript numbers increase consecutively in the order of increase in potential of the connections. If

there is more than one independent d.c. output, the one of lowest power rating shall be marked as indicated herein. The other outputs shall be marked similarly except that 10, 20, 30 and so on, shall be used as the subscript numbers, when determined as shown herein, in the order of increasing power output.

Control connections. — The markings of the control connections shall correspond to the above output markings.

5.10 Regulator sets, generator voltage. — Unless otherwise specified herein, connections to generators, including field windings, shall be marked the same as the leads of the generators based on standard direction of rotation:

D.c. generators.....	(See 5.1.)
A.c. generators.....	(See 5.2.)
Rotary amplifiers.....	(See 5.1.)

Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring agency or as directed by the contracting officer.

Copies of this standard for MILITARY use may be obtained as indicated in the forward to the Index of Military Specifications and Standards.

Copies of this standard may be obtained for other than official use by individuals, firms, and contractors from the Superintendent of Documents, U. S. Government Printing Office, Washington 25, D. C.

Both the title and identifying symbol number should be stipulated when requesting copies of MILITARY standards.

#### Custodians:

Army—Corps of Engineers  
 Navy—Bureau of Ships  
 Air Force

#### Other Interest:

Army—HQDA/T  
 Navy—ANCO/Y




Figure 1 - Series generator without commutating field.




Figure 2 - Shunt generator with commutating field.




Figure 3 - Compound generator without commutating field.




Figure 4 - Compound generator with commutating and compensating fields.



MIL-STD-195  
20 October 1955




Figure 5 - Shunt generator without commutating field.




Figure 6 - Shunt generator with commutating and compensating fields.




Figure 7 - Compound generator with commutating field, but without equalizer connection.




Figure 8 - Three-wire shunt generator without commutating field.




Figure 9 - Three-wire shunt generator with commutating field.




Figure 10 - Three-wire compound generator without commutating field.




Figure 11 - Three-wire compound generator with commutating field.

MIL-STD-193  
20 October 1965




Figure 12 - Shunt motor, nonreversing, without commutating field, two leads brought out.




Figure 13 - Shunt motor, nonreversing, without commutating field, three leads brought out.




Figure 14 - Shunt motor, reversing without commutating field.




Figure 15 - Shunt motor, nonreversing, with commutating field, two leads brought out.




Figure 16 - Shunt motor, nonreversing, with commutating field, three leads brought out.




Figure 17 - Shunt motor, reversing, with commutating field.

MIL-STD-196  
20 October 1965




Figure 18 - Series motor, nonreversing, without commutating field.




Figure 19 - Series motor, reversing, without commutating field.




Figure 20 - Series motor, nonreversing, with commutating field.




Figure 21 - Series motor, reversing, with commutating field.




Figure 22 - Series motor, reversing, without commutating field, split-series.




Figure 23 - Compound motor, nonreversing, without commutating field, two leads brought out.




Figure 24 - Compound motor, nonreversing, without commutating field, three leads brought out.

MIL-STD-195  
29 October 1955




Figure 25 - Compound motor, reversing, without commutating field.




Figure 26 - Compound motor, nonreversing, with commutating field, two leads brought out.




Figure 27 - Compound motor, nonreversing, with commutating field, three leads brought out.




Figure 28 - Compound motor, reversing, with commutating field, five leads brought out.




Figure 29 - Compound motor, reversing, with commutating field, six leads brought out.




Figure 30 - Compound motor, reversing, with compensating and commutating fields, six leads brought out.



MIL-STD-155  
29 October 1959




Figure 31 - Single-phase synchronous generator or motor.





Figure 32 Single-phase, dual-voltage motor.



		L1	L2
One direction rotation	Start	T1, T5	T4, T8
	Run	T1	T4
Other direction rotation	Start	T4, T8	T1, T5
	Run	T4	T1

Figure 33 - Single-phase motor, reversible split-phase with automatic cut-out






Figure 34 - Single-phase motor, nonreversible, split-phase with automatic cut-out.

MIL-STD-145  
20 October 1965



		L <sub>1</sub>	L <sub>2</sub>	Open
One direction rotation	Start	T <sub>1</sub> , T <sub>5</sub>	T <sub>4</sub> , T <sub>8</sub>	-----
	Run	T <sub>1</sub>	T <sub>4</sub>	T <sub>5</sub> , T <sub>8</sub>
Other direction rotation	Start	T <sub>4</sub> , T <sub>5</sub>	T <sub>1</sub> , T <sub>8</sub>	-----
	Run	T <sub>4</sub>	T <sub>1</sub>	T <sub>5</sub> , T <sub>8</sub>

Figure 35 - Single-phase motor, reversible, split-phase, with manual cut-out.



NOTE: To be connected to capacitors in accordance with manufacturer's diagram.

Figure 36 - Single-phase capacitor-start capacitor-run motor and single-phase capacitor-start induction-run motor.




Figure 37 - Single-phase motor, reversible, split-phase, permanent capacitor.




Figure 38 - Single-phase motor, induction with starter non-reversibility.

MIL-STD-175  
20 October 1955





Figure 39 - Single-phase motor, series universal, nonreversing, without compensating fields.



	L1	L2	The together
One direction rotation	A1	S2	A2, S1
Other direction rotation	A1	S1	A2, S2

Figure 40 - Single-phase motor, series universal, reversing, without compensating fields.





Figure 41 - Single-phase motor, series, with conductively compensated separate stator windings.



	L1	L2	Tie together
One direction rotation	A1	S1	S to T1 and A2 to T2
Other direction rotations	A1	S2	S1 to T1 and A2 to T2

Figure 42 - Single-phase motor, series, reversible, with conductively compensated separate stator windings.

MIL-STD-705  
29 October 1955




Figure 43 - Single-phase motor, series, with inductively compensated separate stator windings.




Figure 44 - Repulsion, repulsion-induction and repulsion-start induction run, all single-voltage and without compensating windings.




Figure 45 - Repulsion, repulsion-induction and repulsion-start induction run, all double voltage and without compensating windings.




Figure 46 - Repulsion, repulsion-induction and repulsion-start induction run, all single-voltage reversible.



MIL-STD-105  
20 October 1955





Figure 47 - Repulsion motor, single voltage, inductively compensated.



	L <sub>1</sub>	L <sub>2</sub>	T <sub>1</sub> together
Low voltage	T <sub>1</sub> , T <sub>3</sub>	T <sub>2</sub> , T <sub>4</sub>	-----
High voltage	T <sub>1</sub>	T <sub>4</sub>	T <sub>2</sub> , T <sub>3</sub>

Figure 48 - Repulsion motor, double voltage, inductively compensated.




Figure 49 - Diagram for two circuits per phase.




Figure 50 - Connection markings for two circuits per phase.




Figure 51 - Connection markings for two circuits in parallel per phase.

MIL-STD-193  
20 October 1955




Figure 52 - Connection markings for two circuits in parallel per phase, permanently connected.




Figure 53 - Connection markings for series or parallel connections.






Figure 54 - Connection markings for delta-connected windings.



Speed	L1	L2	L3	Open	T1s together
Low	T1	T2	T3	T4, T5, T6	-----
High	T6	T4	T5	-----	T1, T2, T3


Figure 55 - Variable torque motor.

MIL-STD-155  
20 October 1965




Speed	L1	L2	L3	Open	T4s together
Low	T1	T2	T3	T4, T5, T6	-----
High	T6	T4	T5	-----	T1, T2, T3

Figure 56 - Constant torque motor, arrangement 1.




Speed	L1	L2	L3	Open	T4s together
Low	T1	T2	T3, T7	T4, T5, T6	-----
High	T6	T4	T5	-----	T1, T2, T3, T7

Figure 57 - Constant torque motor, arrangement 2.



Speed	L1	L2	L3	Open	Ts together
Low	T1	T2	T3	-----	T4, T5, T6
High	T6	T4	T5	T1, T2, T3	-----


Figure 58 - Constant horsepower motor, arrangement 1.



Speed	L1	L2	L3	Open	Ts together
Low	T1	T2	T3	-----	T4, T5, T6, T7
High	T6	T4	T5, T7	T1, T2, T3	-----


Figure 59 - Constant horsepower motor, arrangement 2.

MIL-STD-195  
20 October 1955




Speed	L <sub>1</sub>	L <sub>2</sub>	L <sub>3</sub>	Open	T1s together
Low	T <sub>1</sub>	T <sub>2</sub>	T <sub>3</sub>	T <sub>11</sub> , T <sub>12</sub> , T <sub>13</sub> , T <sub>17</sub> , T <sub>21</sub> , T <sub>22</sub> , T <sub>23</sub>	-----
Second	T <sub>11</sub>	T <sub>12</sub>	T <sub>13</sub> , T <sub>17</sub>	T <sub>1</sub> , T <sub>2</sub> , T <sub>3</sub> , T <sub>21</sub> , T <sub>22</sub> , T <sub>23</sub>	-----
High	T <sub>21</sub>	T <sub>22</sub>	T <sub>23</sub>	T <sub>1</sub> , T <sub>2</sub> , T <sub>3</sub> , T <sub>11</sub> , T <sub>12</sub> , T <sub>13</sub> , T <sub>17</sub>	-----

Figure 60 - Three-speed motor using three windings.



Speed	L <sub>1</sub>	L <sub>2</sub>	L <sub>3</sub>	Open	T1s together
Low	T <sub>1</sub>	T <sub>2</sub>	T <sub>3</sub>	T <sub>4</sub> , T <sub>5</sub> , T <sub>6</sub>	-----
Second	T <sub>11</sub>	T <sub>12</sub>	T <sub>13</sub>	T <sub>14</sub> , T <sub>15</sub> , T <sub>16</sub>	-----
Third	T <sub>6</sub>	T <sub>4</sub>	T <sub>5</sub>	-----	T <sub>1</sub> , T <sub>2</sub> , T <sub>3</sub>
High	T <sub>16</sub>	T <sub>14</sub>	T <sub>15</sub>	-----	T <sub>11</sub> , T <sub>12</sub> , T <sub>13</sub>

Figure 61 - Four-speed motor using two windings.



Speed	L1	L2	L3	Open	Tie together
Low	T1	T2	T3, T7	T4, T5, T8	T1, T2, T3, T7
Second	T6	T4	T5	-----	-----
High	T11	T12	T13	-----	-----

Figure 62 - Three-speed motor using two windings.




Figure 63 - Diagram for three circuits per phase.



MIL-STD-195  
20 October 1955




Figure 84 - Connection markings for three circuits per phase.




Figure 85 - Connection markings for three circuits in parallel per phase - all circuit leads brought out.





Figure 66 - Connection markings for three circuits per phase connected in parallel inside the motor.



Speed	L1	L3	L2	L4	Open
Low	T1	T5	T2	T6	T3, T4
High	T1, T6	T3	T2, T6	T4	-----

Figure 67 - Two-speed, two-phase variable torque.

MIL-STD-193  
20 October 1955






Figure 68 - Two-speed motor using two single-speed windings.



Speed	L1	L3	L2	L4	Open
Low	T1	T5	T2	T6	T3, T4
Second	T11	T15	T12	T16	T13, T14
Third	T1, T5	T3	T2, T6	T4	-----
High	T11, T15	T13	T12, T16	T14	-----

Figure 69 - Four-speed motor using two windings.



Speed	L1	L3	L2	L4	Open
Low	T1	T3	T2	T4	
Second	T11	T13	T12	T14	T15, T16
High	T11, T16	T13	T15, T16	T14	

Figure 70 - A three-speed motor using two windings.






Figure 71 - Three-phase, wye-connected aircraft motor with six leads brought out.

241-571-105  
20 October 1955



00007

Figure 72 - Three-phase, wye-connected aircraft motor with phases initially separated for dielectric tests.



00000

Figure 73 - Three-phase, wye-connected aircraft motor.




Figure 74 - Standard two- and three-phase collector ring motor (usual connection wye).




Figure 75 - Two- and three-phase collector ring induction motors, with two-phase rotor.

MIL-STD-155  
20 October 1955




Figure 76 - Shunt-wound three-phase synchronous converter without commutating field.




Figure 77 - Shunt-wound three-phase synchronous converter with commutating field.




Figure 78 - Shunt-wound six-phase synchronous converter without commutating field.




Figure 79 - Shunt-wound six-phase synchronous converter with commutating field.



MIL-STD-155  
20 October 1955




Figure 80 - Compound-wound six-phase synchronous converter without commutating field.




Figure 81 - Compound-wound six-phase synchronous converter with commutating field.




Figure 82 - Compound-wound three-phase synchronous converter without commutating field.




Figure 83 - Compound-wound three-phase synchronous converter with commutating field.

MIL-STD-155  
20 October 1955

**SUBSTRACTIVE POLARITY**




Figure 84

**ADDITIVE POLARITY**




Figure 85

Single-phase transformers, simple  
H and X windings with taps.

**SUBSTRACTIVE POLARITY**




Figure 86 - Single-phase transformers, series  
multiple X windings without taps.

ADDITIVE POLARITY




Figure 87 - Single-phase transformers, series multiple X winding with taps.

SUBTRACTIVE POLARITY






Figure 88 - Auto-transformer.

MIL-STD-180  
20 October 1955



Single-phase transformers, three-wire series connection where neutral is brought out between other two leads.



Single-phase transformers, two-wire parallel connection where neutral is brought out between other two leads.

SUBTRACTIVE POLARITY




Figure 93

ADDITIVE POLARITY




Figure 94

Single-phase transformers, two-wire series connection.

SUBTRACTIVE POLARITY




Figure 95

ADDITIVE POLARITY




Figure 96

Single-phase transformers, two-wire parallel connection.

SUBTRACTIVE POLARITY




Figure 97

ADDITIVE POLARITY






Figure 98

Single-phase transformers, 120-volt class connection.


MIL-STD-195  
20 October 1955



Single-phase transformers, above 120-volt class connection.



Single-phase transformers, three-wire series connection transformer where neutral is brought out to side.



Two-wire parallel connection transformer where neutral is brought out to side.




Figure 105 - Connections for transformers in parallel.




Figure 106 - Three-phase transformers without taps, angular displacement 0 degree.



MIL-STD-195  
29 October 1955  
208




Figure 107 - Three-phase transformers without taps, angular displacement 30 degrees.





Figure 108 - Three-phase transformers with taps, angular displacement 30 degrees.



00294

Figure 109 - Angular displacement and connections - single-phase transformers connected delta-delta and wye-wye in three-phase banks with 0 degree angular displacement.

MLL-STD-195  
20 October 1955




Figure 110 - Angular displacement and connections - single-phase transformers connected delta-wye and wye-delta in three-phase banks with 30 degrees angular displacement.




Figure 111 - Three-phase transformers connected delta - delta and wye-wye with 0 degree angular displacement.

MIL-STD-193  
20 October 1955




Figure 112 - Three-phase transformers connected delta-wye and wye-delta with 30 degrees angular displacement.