MIL-STD-1270A(WC)

Notice 1 26 August 1966

#### **MILITARY STANDARD**

# PATCHING OF WOOD STOCKS FOR THE 7.62MM, M14, AND M14E2 RIFLES

TO ALL HOLDERS OF MIL-STD-1270A (WC)

- 1. MIL-STD-1270A (WC), 18 March 1966 is changed as follows:
- 2. Remove old pages and insert new pages as indicated below.

Old pp	New pp	Superseded pp
v, v i	v, vi	v, vi
13, 14	13, 14	13
15, 16	15, 16	15
17, 18	17, 18	17
21, 22	21, 22	22
25, 26	25, 26	25
31, 32	31, 32	31, 32
33, 34, 35	33, 34, 35	

- 3. Retain this notice and insert before the table of contents.
- 4. Holders of MIL-STD-1270A (WC) will verify that page changes indicated above have been entered. The latest notice (notice page) will be retained as a check sheet. This issuance, together with appended pages, is a separate publication. Each notice is to be retained by stocking points until the Military Standard is completely revised or cancelled.

Custodian: Preparing activity:

Army—WC Army—WC

Project No. 1005-A378

FSC 1005

Downloaded from http://www.everyspec.com

### CONTENTS

1	SCOPE
2	REFERENCED DOCUMENTS
3	DEFINITIONS
4	GENERAL REQUIREMENTS
5	DETAIL REQUIREMENTS
5.1	Materials
5.2	Storage and Preparation of Adhesive
5.3	Patches
5.4	Fillers
	FIGURES
1.	Stock areas
1A.	Pistol grip area, M14E2 rifle stock
2.	Edge split defect
2A.	Edge split defect, patched
3.	Split defect
BA.	Split defect, patched
4.	Knothole defect
<b>1</b> Α.	Knothole defect, patched
5.	Scant material defect
5A.	Scant material defect, patched
6.	Edge split defect
6A.	Edge split defect, patched
7.	Knothole defect
7A.	Knothole defect, patched
8.	Cutter marks and edge split defects
8A.	Cutter marks and edge split defects,
	patched
9.	Edge split defect

### FIGURES-(cont'd)

9A.	Edge split defect, patched	17
10.	Edge split defect	18
10A.	Edge split defect, patched	18
11.	Edge split defect	19
11A.	Edge split defect, patched	19
12.	Knot defect	20
12A.	Knot defect, patched	20
13.	Edge split defect	21
13A.	Edge split defect, patched	22
14.	Corner split	23
14A.	Corner split, patched	23
15.	Crack, front end	24
15A.	Crack, front end, patched	24
15B.	Front end and forearm area M14E2	25
16.	Workmanship defect, patched	26
17.	Knothole defect	26
17A.	Knothole defect, filled	27
18.	Open defect	27
18A.	Open defect, filled	28
19.	Small knothole defect	28
19A.	Small knothole defect, filled	29
20.	Small knothole defect	30
20A.	Small knothole defect, filled	30
21.	Not acceptable patch	31
22.	Not acceptable patch	31
23.	Not acceptable patch	32
24.	Not acceptable patch	33
25.	Not acceptable patch	33
26.	Not acceptable patch	34
27.	Not acceptable patch	34
28.	Not acceptable patch	35





Figure 5. Scant material defect



Patching permitted on right side only Figure 5A. Scant material defect, patched.

MIL-STD-1270A(WC) 18 March 1966





FIGURE 6. Edge split defect.







FIGURE 7. Knothole defect.



Patching permitted on right side only Figure 7A. Knothole defect, patched.

#### MIL-STD-1270A(WC) 18 MARCH 1966



FIGURE 8. Cutter marks and edge split defect.







FIGURE 9. Edge split defect.



Patching permitted on right side only Figure 9A. Edge split defect, patched.

#### MIL-STD-1270A(WC) 18 March 1966




FIGURE 10. Edge split defect.




Figure 10A. Edge split defect, patched.

MIL-STD-1270A(WC) 18 March 1966






FIGURE 13. Edge split defect.



Patching permitted on right side only Figure 13A. Edge split defect, patched.



A. Maximum length of front end patch illustrated in figure 15A. A equals 14 inch.

B. No patches permitted on bottom surface of forearm area. B extends to receiver opening.

FIGURE 15B. Front end and forearm area, M14E2.

#### MIL-STD-1270A(WC) 18 March 1966




Figure 16. Workmanship defect, patched.







FIGURE 17. Knothole defect.




Patch exceeds size limits and extends into area where patching is not permitted






Length of patch exceeds the 1 inch permitted in this area. Figure 22. Not acceptable patch.




Length of patch exceeds one inch permitted in this area


Figure 23. Not acceptable patch.




Patch extends into area where patching is not permitted Figure 24. Not acceptable patch.




Patch exceeds size limits and extends into area where patching is not permitted Figure 25. Not acceptable patch.



Patch exceeds size limits and extends into area where patching is not permitted. Figure 26. Not acceptable patch.



Workmanship defect. Patch has poor mechanical fit and wide glue line Figure 27. Not acceptable patch.



Patch applied to where patching is not permitted. Figure 28. Not acceptable patch.

\* U . S. GOVERNMENT PRINTING OFFICE: 251-069-1966-(X-106)

Downloaded from http://www.everyspec.com