

NOTICE OF GROUP CANCELLATION
---------------------------------

INCH-POUND
------------

MIL-W-22759E  
NOTICE 1  
8 December 2004

# MILITARY SPECIFICATION

WIRE, ELECTRICAL, FLUOROPOLYMER-INSULATED, COPPER OR COPPER ALLOY

MIL-W-22759E, the following specification sheets associated with MIL-W-22759, and current amendments and notices are hereby canceled:

<u>Document</u>	<u>Date</u>	<u>Cancellation Notice No.</u>	<u>DoD Project No.</u>	<u>Replacement</u>
MIL-W-22759E	31-Dec-90	1	6145-2378	SAE-AS22759
MIL-W-22759/1F	18-Sep-92	1	6145-2378-001	SAE-AS22759/1
MIL-W-22759/2G	15-Mar-94	1	6145-2378-002	SAE-AS22759/2
MIL-W-22759/3D	10-Sep-76	1	6145-2378-003	SAE-AS22759/3
MIL-W-22759/4C	10-Apr-92	1	6145-2378-004	SAE-AS22759/4
MIL-W-22759/5B	19-Jul-74	2	6145-2378-005	SAE-AS22759/5
MIL-W-22759/6B	19-Jul-74	2	6145-2378-006	SAE-AS22759/6
MIL-W-22759/7B	19-Jul-74	2	6145-2378-007	SAE-AS22759/7
MIL-W-22759/8B	19-Jul-74	2	6145-2378-008	SAE-AS22759/8
MIL-W-22759/9B	19-Jul-74	2	6145-2378-009	SAE-AS22759/9
MIL-W-22759/10B	19-Jul-74	2	6145-2378-010	SAE-AS22759/10
MIL-W-22759/11F	10-Sep-76	1	6145-2378-011	SAE-AS22759/11
MIL-W-22759/12F	10-Sep-76	1	6145-2378-012	SAE-AS22759/12
MIL-W-22759/13D	29-Jun-73	1	6145-2378-013	SAE-AS22759/13
MIL-W-22759/14B	29-Jun-73	1	6145-2378-014	SAE-AS22759/14
MIL-W-22759/15B	29-Jun-73	1	6145-2378-015	SAE-AS22759/15
MIL-W-22759/16A	10-Mar-81	1	6145-2378-016	SAE-AS22759/16
MIL-W-22759/17A	10-Mar-81	1	6145-2378-017	SAE-AS22759/17
MIL-W-22759/18A	10-Mar-81	1	6145-2378-018	SAE-AS22759/18
MIL-W-22759/19A	10-Mar-81	1	6145-2378-019	SAE-AS22759/19
MIL-W-22759/20	28-Jan-74	2	6145-2378-020	SAE-AS22759/20
MIL-W-22759/21	28-Jan-74	2	6145-2378-021	SAE-AS22759/21
MIL-W-22759/22	28-Jan-74	2	6145-2378-022	SAE-AS22759/22

MIL-W-22759E  
NOTICE 1

<u>Document</u>	<u>Date</u>	<u>Cancellation Notice No.</u>	<u>DoD Project No.</u>	<u>Replacement</u>
MIL-W-22759/23	28-Jan-74	2	6145-2378-023	SAE-AS22759/23
MIL-W-22759/28	15-Jun-76	1	6145-2378-024	SAE-AS22759/28
MIL-W-22759/29	15-Jun-76	1	6145-2378-025	SAE-AS22759/29
MIL-W-22759/30	15-Jun-76	1	6145-2378-026	SAE-AS22759/30
MIL-W-22759/31	15-Jun-76	1	6145-2378-027	SAE-AS22759/31
MIL-W-22759/32C	9-Sep-88	1	6145-2378-028	SAE-AS22759/32
MIL-W-22759/33C	9-Sep-88	1	6145-2378-029	SAE-AS22759/33
MIL-W-22759/34D	9-Sep-88	1	6145-2378-030	SAE-AS22759/34
MIL-W-22759/35D	9-Sep-88	1	6145-2378-031	SAE-AS22759/35
MIL-W-22759/41C	9-Sep-88	1	6145-2378-032	SAE-AS22759/41
MIL-W-22759/42B	9-Sep-88	1	6145-2378-033	SAE-AS22759/42
MIL-W-22759/43C	9-Sep-88	1	6145-2378-034	SAE-AS22759/43
MIL-W-22759/44A	9-Sep-88	1	6145-2378-035	SAE-AS22759/44
MIL-W-22759/45A	9-Sep-88	1	6145-2378-036	SAE-AS22759/45
MIL-W-22759/46A	9-Sep-88	1	6145-2378-037	SAE-AS22759/46
MIL-DTL-22759/80A	23-Feb-98	1	6145-2378-038	SAE-AS22759/80
MIL-DTL-22759/81A	23-Feb-98	1	6145-2378-039	SAE-AS22759/81
MIL-DTL-22759/82A	23-Feb-98	1	6145-2378-040	SAE-AS22759/82
MIL-DTL-22759/83A	23-Feb-98	1	6145-2378-041	SAE-AS22759/83
MIL-DTL-22759/84A	23-Feb-98	1	6145-2378-042	SAE-AS22759/84
MIL-DTL-22759/85A	23-Feb-98	1	6145-2378-043	SAE-AS22759/85
MIL-DTL-22759/86A	23-Feb-98	1	6145-2378-044	SAE-AS22759/86
MIL-DTL-22759/87A	23-Feb-98	1	6145-2378-045	SAE-AS22759/87
MIL-DTL-22759/88A	23-Feb-98	1	6145-2378-046	SAE-AS22759/88
MIL-DTL-22759/89A	23-Feb-98	1	6145-2378-047	SAE-AS22759/89
MIL-DTL-22759/90A	23-Feb-98	1	6145-2378-048	SAE-AS22759/90
MIL-DTL-22759/91A	23-Feb-98	1	6145-2378-049	SAE-AS22759/91
MIL-DTL-22759/92A	23-Feb-98	1	6145-2378-050	SAE-AS22759/92

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

(Application for copies of SAE-Aerospace Standards should be addressed to SAE,  
400 Commonwealth Drive, Warrendale, PA 15096-0001.)

MIL-W-22759E  
NOTICE 1

Custodians:

Army - CR  
Navy - AS  
Air Force - 11  
DLA - CC  
NASA - NA

Preparing activity:

Navy - AS

(Project No. 6145-2378)

Review activities:

Army - AR, AT, AV, CR4, MI  
Navy - EC, MC, OS  
Air Force - 71

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information using the ASSIST Online database at <http://assist.daps.dla.mil>.