

| |
|---------------------------|
| NOTICE OF CANCELLATION |
|---------------------------|

| |
|------------|
| INCH-POUND |
|------------|

MS24398 Rev. H
NOTICE 2
23 February 2001

MILITARY STANDARD

ADAPTER, STRAIGHT, TUBE TO BOSS, PRECISION TYPE

MS24398 Rev. H, dated 10 February 1984, is hereby cancelled. Future acquisitions for this item should refer to the Society of Automotive Engineers (SAE) Aerospace Standard, AS5173, "Fitting, Bushing, Port, Reducer".

Table I provides a detailed cross-reference of cancelled MS24398 Part or Identifying Numbers (PINs) and replacement AS5173 PINs. The use of AS5173 parts is preferable, but MS parts may be used for a period of three years from the date of this notice to deplete existing stock. Users are cautioned to evaluate replacements for their particular application.

(Copies of SAE AS5173 may be purchased from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096.)

Custodians:

Air Force - 99
Army - AV
Navy - AS
DLA - CC

Preparing activity:

DLA - CC

(Project 4730-2170)

Review activities:

Army - AT
Air Force - 70, 71
Navy - MC, SA

MS24398
NOTICE 2

Table I. Cross-Reference Data

| Cancelled MS PIN | Replacement AS PIN | Cancelled MS PIN | Replacement AS PIN ^{1/} |
|------------------|--------------------|------------------|----------------------------------|
| MS24398-3-2 | AS5173-0302 | MS24398-6-5 | AS5173-0605 |
| MS24398D3-2 | AS5173D0302 | MS24398D6-5 | AS5173D0605 |
| MS24398J3-2 | AS5173J0302 | MS24398J6-5 | AS5173J0605 |
| MS24398K3-2 | AS5173K0302 | MS24398K6-5 | AS5173K0605 |
| MS24398S3-2 | AS5173R0302 | MS24398S6-5 | AS5173R0605 |
| MS24398T3-2 | AS5173T0302 | MS24398T6-5 | AS5173T0605 |
| MS24398W3-2 | AS5173W0302 | MS24398W6-5 | AS5173W0605 |
| MS24398-4-2 | AS5173-0402 | MS24398-8-4 | AS5173-0804 |
| MS24398D4-2 | AS5173D0402 | MS24398D8-4 | AS5173D0804 |
| MS24398J4-2 | AS5173J0402 | MS24398J8-4 | AS5173J0804 |
| MS24398K4-2 | AS5173K0402 | MS24398K8-4 | AS5173K0804 |
| MS24398S4-2 | AS5173R0402 | MS24398S8-4 | AS5173R0804 |
| MS24398T4-2 | AS5173T0402 | MS24398T8-4 | AS5173T0804 |
| MS24398W4-2 | AS5173W0402 | MS24398W8-4 | AS5173W0804 |
| MS24398-4-3 | AS5173-0403 | MS24398-8-5 | AS5173-0805 |
| MS24398D4-3 | AS5173D0403 | MS24398D8-5 | AS5173D0805 |
| MS24398J4-3 | AS5173J0403 | MS24398J8-5 | AS5173J0805 |
| MS24398K4-3 | AS5173K0403 | MS24398K8-5 | AS5173K0805 |
| MS24398S4-3 | AS5173R0403 | MS24398S8-5 | AS5173R0805 |
| MS24398T4-3 | AS5173T0403 | MS24398T8-5 | AS5173T0805 |
| MS24398W4-3 | AS5173W0403 | MS24398W8-5 | AS5173W0805 |
| MS24398-5-4 | AS5173-0504 | MS24398-8-6 | AS5173-0806 |
| MS24398D5-4 | AS5173D0504 | MS24398D8-6 | AS5173D0806 |
| MS24398J5-4 | AS5173J0504 | MS24398J8-6 | AS5173J0806 |
| MS24398K5-4 | AS5173K0504 | MS24398K8-6 | AS5173K0806 |
| MS24398S5-4 | AS5173R0504 | MS24398S8-6 | AS5173R0806 |
| MS24398T5-4 | AS5173T0504 | MS24398T8-6 | AS5173T0806 |
| MS24398W5-4 | AS5173W0504 | MS24398X8-6 | AS5173W0806 |
| MS24398-6-4 | AS5173-0604 | MS24398-10-4 | AS5173-1004 |
| MS24398D6-4 | AS5173D0604 | MS24398D10-4 | AS5173D1004 |
| MS24398J6-4 | AS5173J0604 | MS24398J10-4 | AS5173J1004 |
| MS24398K6-4 | AS5173K0604 | MS24398K10-4 | AS5173K1004 |
| MS24398S6-4 | AS5173R0604 | MS24398S10-4 | AS5173R1004 |
| MS24398T6-4 | AS5173T0604 | MS24398T10-4 | AS5173T1004 |
| MS24398W6-4 | AS5173W0604 | MS24398W10-4 | AS5173W1004 |

^{1/} The SAE replacement part is a functional equivalent of the military part except that some sizes require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.

MS24398
NOTICE 2

Table I. Cross-Reference Data (Continued)

| Cancelled MS PIN | Replacement AS PIN <u>1/</u> | Cancelled MS PIN | Replacement AS PIN <u>1/</u> |
|------------------|---------------------------------|------------------|------------------------------|
| MS24398-10-5 | AS5173-1005 | MS24398-12-10 | AS5173-1210 |
| MS24398D10-5 | AS5173D1005 | MS24398D12-10 | AS5173D1210 |
| MS24398J10-5 | AS5173J1005 | MS24398J12-10 | AS5173J1210 |
| MS24398K10-5 | AS5173K1005 | MS24398K12-10 | AS5173K1210 |
| MS24398S10-5 | AS5173R1005 | MS24398S12-10 | AS5173R1210 |
| MS24398T10-5 | AS5173T1005 | MS24398T12-10 | AS5173T1210 |
| MS24398W10-5 | AS5173W1005 | MS24398W12-10 | AS5173W1210 |
| MS24398-10-6 | AS5173-1006 | MS24398-16-6 | AS5173-1606 |
| MS24398D10-6 | AS5173D1006 | MS24398D16-6 | AS5173D1606 |
| MS24398J10-6 | AS5173J1006 | MS24398J16-6 | AS5173J1606 |
| MS24398K10-6 | AS5173K1006 | MS24398K16-6 | AS5173K1606 |
| MS24398S10-6 | AS5173R1006 | MS24398S16-6 | AS5173R1606 |
| MS24398T10-6 | AS5173T1006 | MS24398T16-6 | AS5173T1606 |
| MS24398W10-6 | AS5173W1006 | MS24398W16-6 | AS5173W1606 |
| MS24398-10-8 | AS5173-1008 | MS24398-16-8 | AS5173-1608 |
| MS24398D10-8 | AS5173D1008 | MS24398D16-8 | AS5173D1608 |
| MS24398J10-8 | AS5173J1008 | MS24398J16-8 | AS5173J1608 |
| MS24398K10-8 | AS5173K1008 | MS24398K16-8 | AS5173K1608 |
| MS24398S10-8 | AS5173R1008 | MS24398S16-8 | AS5173R1608 |
| MS24398T10-8 | AS5173T1008 | MS24398T16-8 | AS5173T1608 |
| MS24398W10-8 | AS5173W1008 | MS24398W16-8 | AS5173W1608 |
| MS24398-12-6 | AS5173-1206 | MS24398-16-10 | AS5173-1610 |
| MS24398D12-6 | AS5173D1206 | MS24398D16-10 | AS5173D1610 |
| MS24398J12-6 | AS5173J1206 | MS24398J16-10 | AS5173J1610 |
| MS24398K12-6 | AS5173K1206 | MS24398K16-10 | AS5173K1610 |
| MS24398S12-6 | AS5173R1206 | MS24398S16-10 | AS5173R1610 |
| MS24398T12-6 | AS5173T1206 | MS24398T16-10 | AS5173T1610 |
| MS24398W12-6 | AS5173W1206 | MS24398W16-10 | AS5173W1610 |
| MS24398-12-8 | AS5173-1208 | MS24398-16-12 | AS5173-1612 |
| MS24398D12-8 | AS5173D1208 | MS24398D16-12 | AS5173D1612 |
| MS24398J12-8 | AS5173J1208 | MS24398J16-12 | AS5173J1612 |
| MS24398K12-8 | AS5173K1208 | MS24398K16-12 | AS5173K1612 |
| MS24398S12-8 | AS5173R1208 | MS24398S16-12 | AS5173R1612 |
| MS24398T12-8 | AS5173T1208 | MS24398T16-12 | AS5173T1612 |
| MS24398W12-8 | AS5173W1208 | MS24398W16-12 | AS5173W1612 |

1/ The SAE replacement part is a functional equivalent of the military part except that some require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.

MS24398
NOTICE 2

Table I. Cross-Reference Data (Continued)

| Cancelled MS PIN | Replacement AS PIN ^{1/} | Cancelled MS PIN | Replacement AS PIN ^{1/} |
|------------------|----------------------------------|------------------|----------------------------------|
| MS24398-20-8 | AS5173-2008 | MS24398-20-12 | AS5173-2012 |
| MS24398D20-8 | AS5173D2008 | MS24398D20-12 | AS5173D2012 |
| MS24398J20-8 | AS5173J2008 | MS24398J20-12 | AS5173J2012 |
| MS24398K20-8 | AS5173K2008 | MS24398K20-12 | AS5173K2012 |
| MS24398S20-8 | AS5173R2008 | MS24398S20-12 | AS5173R2012 |
| MS24398T20-8 | AS5173T2008 | MS24398T20-12 | AS5173T2012 |
| MS24398W20-8 | AS5173W2008 | MS24398W20-12 | AS5173W2012 |
| MS24398-20-10 | AS5173-2010 | MS24398-20-16 | AS5173-2016 |
| MS24398D20-10 | AS5173D2010 | MS24398D20-16 | AS5173D2016 |
| MS24398J20-10 | AS5173J2010 | MS24398J20-16 | AS5173J2016 |
| MS24398K20-10 | AS5173K2010 | MS24398K20-16 | AS5173K2016 |
| MS24398S20-10 | AS5173R2010 | MS24398S20-16 | AS5173R2016 |
| MS24398T20-10 | AS5173T2010 | MS24398T20-16 | AS5173T2016 |
| MS24398W20-10 | AS5173W2010 | MS24398W20-16 | AS5173W2016 |

^{1/} The SAE replacement part is a functional equivalent of the military part except that some sizes require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.