

ADMINISTRATIVE
NOTICE

INCH-POUND

MS17820
NOTICE 3
16 August 2010
SUPERSEDING
NOTICE 2
16 June 1997

DETAIL SPECIFICATION SHEET

INSERT, HELICAL COIL INSTALLATION THREAD,
DESIGN STANDARD FOR

Inactive for new design after 16 June 1997

The Federal Supply Class (FSC) for MS17820 has changed from 5340 to 5325. Comments, suggestions, or questions on this document should be addressed to Defense Supply Center Philadelphia (DSCP), ATTN: DSCP-NASA, 700 Robbins Avenue, Philadelphia, PA 19111-5096 or email to dscpg&ispeccomments@dla.mil.

Custodians:
Army - AV

Preparing activity:
DLA - IS

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST online database at <https://assist.daps.dla.mil>.

AMSC N/A

FSC 5325