#### DATA ITEM DESCRIPTION:

Title: VALIDATOR NOTES REPORT

Number: DI-MGMT-81778 Approval Date: 20091001

AMSC Number: N9083 Limitation:

DTIC Applicable: N/A GIDEP Applicable: N/A

Office of Primary Responsibility: SEA 04L122

Applicable Forms:

Use Relationship: The Validator Notes Report will be used to evaluate

and explain the errors found during a validation of the ship.

This Data item Description (DID) contains the format and content preparation instructions for the data product generated by a specific and discrete task requirement as delineated in the contract.

## Requirements:

- 1. <u>Format</u>. The Validator Notes Report shall be presented in the contractor's format.
- 2. <u>Content.</u> The report shall contain all of the information specified in figure 1 of this DID.
- 3. End of DI-MGMT-81776

# Figure - 1

# Validator Notes for USS Mahan DDG-72

The following Notes were submitted by NAVSEA SCLSIS Audit Team Validators during the 17-24AUG09 shipcheck of USS Mahan DDG-72.

**RIN 001MS**ALT DATA VERIFIED

**RIN 001XM** INACCESSIBLE

**RIN 0029W** ALT DATA VERIFIED

**RIN 002AG** ALT DATA VERIFIED

**RIN 002JZ** ALT DATA VERIFIED

**RIN 002KF** ALT DATA VERIFIED

**RIN 002KR** ALT DATA VERIFIED

RIN 002KU ALT DATA VERIFIED

**RIN 002LJ** ALT DATA VERIFIED

**RIN 002LL** ALT DATA VERIFIED

**RIN 002RH** CHANGE SN TO 05119

**RIN 0033D** ALT DATA VERIFIED

**RIN 0036X** ALT DATA VERIFIED

**RIN 003AC** ALT DATA VERIFIED

**RIN 003AD** ALT DATA VERIFIED

**RIN 003BE** ALT DATA VERIFIED

**RIN 003BL** ALT DATA VERIFIED

**RIN 003CH** ALT DATA VERIFIED

**RIN 003DA** ALT DATA VERIFIE

**RIN 003DC** ALT DATA VERIFIED

**RIN 003DE** ALT DATA VERIFIED

**RIN 003DG** ALT DATA VERIFIED

**RIN 003DY** ALT DATA VERIFIED

**RIN 003EL** NTC. ALT DATA VERIFIED

**RIN 003KN** ALT DATA VERIFIED

**RIN 003KQ** ALT DATA VERIFIED

**RIN 003KW**MISSING ALT LABEL PLATE

**RIN 003PZ** INACCESSIBLE

**RIN 004DS**MISCELLANEOUS EQUIP

**RIN 005PM** PORTABLE

**RIN 0060K** ALT DATA VERIFIED

**RIN 0067S** INACCESSIBLE

## Downloaded from http://www.everyspec.com

## **DI-MGMT-81778**

## RIN 006BQ INACCESSIBLE

## RIN 006LW

**INACCESSIBLE** 

## *RIN 00A7X*

THERE IS NO MARINEFAX IN THE CHART ROOM

## RIN 00AWC

**PORTABLE** 

## RIN 00DHC

INACCESSIBLE

## RIN 00DNP

LOC SHIPWIDE

## RIN 00DVQ

CHANGE LOC TO 1-300-0-C

## RIN 00DWG

CHANGE LOC TO 1-300-0-C

## RIN 00E2G

CHANGE LOC TO 1-300-0-C

## *RIN 00E8C*

CHANGE LOC TO 2-126-2-C

## *RIN 00E8D*

CHANGE LOC TO 2-126-2-C

## RIN 00EEV

NO NAMEPLATE

## RIN 00EEW

INACCESSIBLE

## RIN 00EHA

ALT DATA VERIFIED

## RIN 00EHD

ALT DATA VERIFIED

## RIN 00EKV

ALT DATA VERIFIED

## RIN 00EMJ

ALT DATA VERIFIED

Thursday, August 27, 2009

Page 4 of 13

RIN	00ENY
ALT DA	ATA VERIFIED

## RIN 00EYV

**INACCESSIBLE** 

## RIN 00F1N

INACCESSIBLE

## RIN 00F1P

**INACCESSIBLE** 

## RIN 00F3V

CHANGE LOC TO 01-130-0-Q

## RIN 00F4A

CHANGE LOC TO 01-130-0-Q

# RIN 00GGY

ALT DATA VERIFIED

## RIN 00GXJ

INACCESSIBLE

#### RIN 00GZW

CHANGED TO CORRECT LOCATION

## RIN 00H1D

CHANGE SN TO 08-0295

# RIN 00LFT

CHANGE LOC TO 01-274-1-C

## RIN 00LVO

NTC. CHANGED TO CORRECT LOCATION

## RIN OOLWE

HELO MAINTENANCE FLOODLIGHTS ARE COVERED BY RINS 00LVP, 00LVQ, 00LVR, AND 7H6AS.

## RIN 00M7K

CHANGE SN TO 0029

## RIN 00NCD

NO NAMEPLATE DATA

## RIN OONKR

SHIPWIDE

## RIN 000DF

INACCESSIBLE

## RIN 000MF

INACCESSIBLE

## RIN 00VWQ

CHANGE SN TO EK49

## RIN 2202G

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## **RIN** 7A03T

CONTROLLER HAS PART NUMBER 6962ED3363A AND CROSSES TO RIC 151212279. WILL ADD RECORD IN CDMD-OA WORKFILE

## RIN 7A0FT

**UNABLE TO READ SERIAL NUMBER** 

#### RIN 7A0JK

CHANGE SN TO NC3

#### RIN 7A1CA

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## **RIN** 7A26N

NTC

## *RIN 7A37H*

MISSING ALT LABEL PLATE

## RIN 7A3FL

CHANGED TO CORRECT LOCATION

## RIN 7A3XK

CHANGED TO CORRECT LOCATION

## RIN 7A3YC

INSTALLED IS SYM 616 WITH 8 CKTS. WILL ADD RIC 509990016 IN CDMD-OA WORKFILE

## **RIN** 7A62J

CHANGE PRID TO 2-63-1

## **RIN** 7A65M

NO NAMEPLATE DATA

## **RIN** 7A78N

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7A7MC

NO NAMEPLATE DATA

## RIN 7A7VX

NTC

#### Downloaded from http://www.everyspec.com

## DI-MGMT- 81778

# *RIN 7A80S*

**INACCESSIBLE** 

## RIN 7A84T

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7A8KB

**INACCESSIBLE** 

## **RIN 7A94S**

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

#### RIN 7AX6F

NTC

## RIN 7AYHX

TWO RECORDS LOADED, ONLY ONE SWITCH IS INSTALLED

## RIN 7BB3V

INACCESSIBLE

## RIN 7BBYG

**INACCESSIBLE** 

#### RIN 7BCYG

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

#### RIN 7BF2J

UNABLE TO LOCATE VALVE WITH THIS PRID. NOT SHOWN IN EOP CODE DPR/0337/030306

## RIN 7BF7E

**INACCESSIBLE** 

## RIN 7BGPK

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7BJKH

**INACCESSIBLE** 

## RIN 7BKAX

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7BKDX

Change to Pass - Sight validated by OSLR 8/25 -

OSLR Disagree, sight validated OWT-V-279 (Under the deck plate inboard of the chill water pump) & OWT-V-113. Updated CDMD-OA accordingly.

DELETE 7BKDX. PRID NOT FOUND. PRID NOT SHOWN EOSS DOWS/0291/061201. IAW SAME, OILY WASTE HOLDING TANK FILL VALVE IS OWT-V-113, RIN 7GERX (COULD NOT CONFIRM OTHER THAN BEING SAME SIZE VLV&PSI - NO NP DATA). PRID OWT-V-113 ALSO CROSSED TO RIN 7F16E AS 2" BALL VLV AND SHOULD ALSO BE DELETED.

#### Downloaded from http://www.everyspec.com

## DI-MGMT-81778

## RIN 7BKJA

**INACCESSIBLE** 

## RIN 7BL4X

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

#### RIN 7BLXO

INACCESSIBLE

## RIN 7BLYW

**INACCESSIBLE** 

## RIN 7BMQP

SUSPECT FOUND BEHIND 4AC CONTROL PANEL. UNABLE TO CONFIRM RIC. NO NP DATA.

## RIN 7BMQQ

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## *RIN 7D05E*

DELETE 7D05E. ACTUAL PTNR WAS 0203SH-S0401211, RIC 75A000005. ALREADY SUPPORTED BY RIN 7HJMJ. SN WAS 07-506259-5

## RIN 7D49L

LAGGED

#### RIN 7D5KK

THERE IS NOT ENOUGH DATA IN THE RECORD TO IDENTIFY THE ITEM

#### RIN 7D5RR

**INACCESSIBLE** 

## RIN 7D8HZ

INSTALLED IS AM-2210N, SERIAL NUMBER 2888. WILL ADD RIC 270490092 IN CDMD-OA WORKFILE

## RIN 7DNEU

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7DRVE

**INACCESSIBLE** 

## RIN 7DU8Q

INACC3SSIBLE

## RIN 7DYEZ

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

#### RIN 7E2PV

SUSPECT COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7E2RF

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## **RIN 7E57S**

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

## RIN 7EV6B

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## RIN 7EYXD

NO NAMEPLATE DATA

## RIN 7F0DW

**INACCESSIBLE** 

## RIN 7F0RP

NO NAMEPLATE DATA

## RIN 7F1VK

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## *RIN* 7F38N

THERE IS NOT ENOUGH DATA IN THE RECORDTO IDENTIFY THE ITEM

## RIN 7F3BA

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## RIN 7F6GA

INACCESSIBLE

## RIN 7F9BX

COMPONENT FOUND UNABLE TO CONFIRM RIC- INACCESS

## RIN 7F9HD

NO NAMEPLATE DATA

## RIN 7FBOT

NAMEPLATE DATA IS UNREADABLE

## RIN 7G0FU

INACCESSIBLE

## RIN 7GBAM

NTC

## RIN 7GBFE

DELETE 7GBFE. THIS SAMPLE VALVE IS 1/2" ANL VICE 8" GLB STP CHECK. ADD STAMPED RIC 882002664.

## RIN 7GTNK

**INACCESSIBLE** 

#### RIN 7GUCV

1-254-5-L

NOB: RIN 7GUCV/RIC 614320003

THE CORRECT ACTUATOR VALVE IS 20008-3, RIC 614320013. THE CORRECT VALVE IS FM-V-17 MFR ID-10020-2, RIC 883041372. FM-17 ACTUATOR VALVE MFR ID 20008-3, RIC 614320013 WILL BE AN ADD VIA CDMD-OA.

## RIN 7GX6R

**INACCESSIBLE** 

## RIN 7H01C

CHANGED TO CORRECT LOCATION

#### RIN 7H01D

CHANGED TO CORRECT LOCATION

#### RIN 7H0TK

DELETE 7H0TK. THERE WAS NO HP DEHY. NO DEHY SHOWN EOSS DWG DHPC/0585/071803. NO HPAC OUTLET DEHY FOUND. CLOSEST MATCH - DEHYDRATOR, INTERSTAGE MEMBRANE MDL IMD-60. RIC 448880044. SN 9366 RIN 7H5GY.

#### RIN 7H0UD

DELETE 7H0UD. NO HPAC DEHY FOUND. NOT SHOWN EOSS DWGS. NO 10 VLV MANF FOUND FOR HPAC. CLOSEST MATCH - 5VLV HPAC DRN MANF(NO NP DATA) AND DEHYDRATOR, INTERSTAGE MEMBRANE MDL IMD-60, RIC 448880044, SN 9366 RIN 7H5GY.

#### RIN 7H0YB

DELETE 7H0YB. MFR AIR DRY CORP DEHY WITH DESICANT UNIT AS HIGHER ASSY NOT FOUND. CLOSEST MATCH WAS DEHYDRATOR, INTERSTAGE MEMBRANE MDL IMD-60, RIC 448880044, SN 9366 RIN 7H5GY.

#### RIN 7H0YV

DELETE 7H0YV. AHPV6 NOT FOUND. PRID NOT EOSS DWG DHPC/0585/071803. NO HPAC OUTLET DEHY FOUND. CLOSEST MATCH - DEHYDRATOR, INTERSTAGE MEMBRANE MDL IMD-60, RIC 448880044, SN 9366 RIN 7H5GY.

#### RIN 7H1GN

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

#### RIN 7H1JH

NO NAMEPLATE DATA

#### RIN 7H2EC

LOC PORTABLE

## RIN 7H2EJ

DELETE 7H2EJ. PTNR WAS 07F32AC. ADD 48A990031 IN CDMD.

## RIN 7H2RZ

THE ONLY 1ELMT PB SW FOUND IN THIS PWAY IS FOR AFFF PMP NO 2 WITH PN 6981ED171-10P. 8/24/09 CHANGED TO PASS AND CHANGED LOCATION.

## *RIN 7H31F*

DELETE 7H31F. DID NOT FIND SEPARATE TEMP CONTROL PNL WITH 3 KNOBS AND CIRCUIT CARD FOR 4AC OR ANY OF OTHER AC UNITS. THERE WEREN'T ANY CIRCUIT CARDS INSIDE YORK MARINEPAK PANEL BOLTED TO FOUNDATIONS OF 1-4AC. 4AC TEMP CONTROL MAINTAINED BY MFR JOHNSON&JOHNSON CONTROL TEMP PNEUM T8000, RIC 610290060 (SEE ZC014) INSIDE SAME.

#### RIN 7H44F

DELETE 7H44F. ACTUAL PTNR WAS 803-2177525-S111. ADD 882057955. PRID 1-FS-V-346.

## RIN 7H4RL

NOT STORED ON WEATHERDECK

## RIN 7H4UH

**CHANGE SN TO BT658** 

## RIN 7H5GA

**INACCESSIBLE** 

#### RIN 7H9UZ

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## RIN 7HGUZ

NO NAMEPLATE DATA

#### RIN 7HH5L

THERE IS NO SMOKE DETECTOR ON THE WEATHERDECK.8/20 CHANGED TO PASS AND CHANGED LOCATION

## RIN 7HJ0C

CONTROLLER 01-248-1 HAS NO ROTARY SWITCH. IT HAS 3 PB SWITCHES FOR START, STOP, AND RESET. PUSH SWITCH IS LISTED UNDER RIC 151212278. SEE ADD RIN ZA000

## RIN 7HJEG

COMPONENT FOUND UNABLE TO CONFIRM RIC - LAGGED

#### RIN 7HT3F

CHANGE LOC TO 1-126-0-C

#### RIN 7HTLL

DELETE, INSTALLED ANTENNAS ARE AS-3771B RIC 00032372 AND ARE CORRECT IN THE DB

## RIN 7HU5A

CHANGE SBN TO A025

## RIN 7HWCP

INACCESSIBLE

## RIN 7HXQW

FOUND MULTIPLE TERMINAL BOXES SYM 400.2. NOT ONE IS LABELED

## RIN 7HYHP

INSUFFICIENT DATA TO CONFIRM RIC

## RIN 7HZKZ

INACCESSIBLE

#### RIN 7J0RE

XHOSE

## RIN 7J0TX

XHOSE0C0002

## RIN 7J10G

ALT DATA VERIFIED

## RIN 7J10L

ALT DATA VERIFIED

#### **RIN 7J10U**

INFO ON THE STICKER ON TOP OF THE WORKSTATION DOES NOT CROSS TO A RIC. HP COMPAQ dx2000MT, hp s/n 2UA5390XH5, p/n DR547AV

#### RIN 7J6NE

THERE ARE NO EMERGENCY ESCAPE BREATHING DEVICE IN THIS LOCATION 1-78-01-L

#### RIN 7J8AM

XHOSE

## RIN 7J8EG

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## RIN 7J8EH

COMPONENT FOUND UNABLE TO CONFIRM RIC NO NP DATA

## RIN 7J8GV

XHOSE

#### RIN 7J8KV

**XHOSE** 

## RIN 7JJ3B

CHANGE LOC TO 1-110-1-L

## RIN ZA000

CONTROLLER CH 6962ED3371A. RECORD IN DATABASE IS RIN 7A7VD WITH INCORRECT RIC. WILL DELETE 7A7VD IN CDMD-OA WORKFILE

## RIN ZB000

ADD SPLIT HEADSET INTERFACE BOX. PN 8100-3527-0120, RIC 27A010001.

#### RIN ZB001

ADD AM-7364(V)2/USC-38(V), HIGH POWER AMP, SN 1076, RIC 00023084.

## RIN ZB002

ADD LS-519E/SIC, INTERCOMMUNICATIONS STATION, SN CB6, RIC 00016018

## RIN ZC000

ZC000 - PTNR BXL2NFD FOR PUMP NO 2, WASTE WATER DRAIN COLLECTING RIC IS NIF. ADD 01A020041. DELETE OLD RIN 7BK7D.

## RIN ZC001

ZC001 - PTNR A94234009A3D FOR ABT 3-290-1 RIC IS NIF. ADD 21A020041. DELETE OLD RIN 7A01X.

## RIN ZC002

ZC002 - STAMPED RIC FOR 2-P-LOS-V-7A NIF. ADD 882002664. DELETE 7GBFF IN CDMD.

#### RIN ZC003

ZC003 - PTNR 803-2177525-C811 FOR 2-LO-V-205 RIC IS NIF. ADD 882056820.

#### RIN ZC004

ZC004 - PTNR 7149-G501 FOR MONITOR DEWPOINT NR1 HPAC RIC IS NIF. ADD 38A010010. 3 MORE RECORDS WILL NEED TO BE ADDED TO DB FOR NR2 HPAC, NR1 AND 2 ELECTRONIC DRY LPAIR (AED) DEHY DEWPOINT MONITORS. SN'S 182, 041 AND 042 RESPECTIVELY.

## RIN ZC005

ZC005 - STAMPED RIC FOR AHP-V-521 IS NIF. ADD 882072169. DELETE 7EVVX IN CDMD.

## RIN ZC006

ZC006 - STAMPED RIC FOR PRID AHP-V-300 IS NIF. ADD 882057652. DELETE 7H3ZW IN CDMD.

#### RIN ZC007

ZC007 - PTNR L22428P10 FOR DETECTOR, ICE (1A GTRB ENCL) RIC IS NIF. ADD 279990387. DELETE 7GU8B IN CDMD.

#### RIN ZC008

ZC008 - STAMPED RIC FOR 1-P-LOS-V-3B IS NIF. ADD 882002664. DELETE 7GBFC IN CDMD. ADD SAME FOR 1-P-LOS-V-3A

#### RIN ZC009

ZC009 - 19NCXXX0X30E1BXAXX02/NIIN 014700330 FOR SW-GA-056 RIC IS NIF. ADD 45A990018. DELETE 7H4HX IN CDMD.

## RIN ZC010

ZC010 - 19NCXXX0X30E1BXAXX02/NIIN 014700330 FOR SW-GA-059 RIC IS NIF. ADD 45A990018. DELETE 7GY9K IN CDMD.

#### RIN ZC011

ZC011 - STAMPED NIIN 012308549 FOR 2AC TANK, OIL DRAIN NR2 RIC IS NIF. ADD 924020124.

#### RIN ZC012

ZC012 - PTNR 07L32BC FOR LUBRICATOR REG PNEU RIC IS NIF. ADD 650070043. DELETE 7H2EM IN CDMD.

#### RIN ZC013

ZC013 - PTNR 19NCXXX0X20E1BXAXX02 FOR CPW-GA-71 RIC IS NIF. ADD 45A990021. DELETE 7GHZG FIN CDMD.

#### RIN ZC014

ZC014 - PTNR T-8000 FOR 4AC CONTROL TEMP PNEUM RIC IS NIF. ADD 610290060. ALL 4 AC'S HAVE SAME.

## RIN ZD000

1-254-5-L

ZD000

NIF: FM-V-17 VALVE GATE 8.00IPS, MFR ID 10020-2, RIC 883041372. THERE IS A RECORD (RIN 7GVYE/ RIC 882293508) IN THE DATABASE BEING USED IN THIS APPLICATION BUT IT DOES NOT MATCH THE DATA ON THE VALVE INSTALLED, THEREFORE, RIN 7GVYE/ RIC 882293508 WILL BE A DELETE VIA CDMD-OA.

## RIN ZD001

1-254-5-L

ZD000

NIF: FM-V-306 VALVE BTFLY ASSY W/ACT, MFR ID 10004-2, RIC 882293508. THERE IS A RECORD (RIN 7GY4P/ RIC 883041372) IN THE DATABASE BEING USED IN THIS APPLICATION BUT IT DOES NOT MATCH THE DATA ON THE VALVE INSTALLED, THEREFORE, RIN 7GY4P/ RIC 883041372 WILL BE A DELETE VIA CDMD-OA